





1-59

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2023/ 170

Dated 02/06/2023

## FIRE SAFETY CERTIFICATE

Certified that the M/s McDonald's Family Restaurant Located at BG-02, Ground floor, Ansal Plaza Shopping Arcades at Hudeo Place at Pinjra Pole, Andrewsganj, New Delhi., comprised of two tier basement, ground, mezzanine plus three upper floor, the Restaurant running at ground floor only owned / occupied by M/s Connaught Plaza Restaurant Pvt. Ltd. was granted Fire Safety Certificate vide letter no.F.6/DFS/MS/EH/SZ/2020/137dated 29/09/2020. The Premise was re-inspected by the officer concerned of this department on 24/05/2023 in the presence of Sh. Devender Singh (Manager)and found that the said eating house at ground floor only have deemed complied with the fire prevention and fire safety requirements in accordance rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" (Group-D) / Eating House with effect from .02/06/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service

Issued on 02/6/2023 at New Delhi by.

(APVL GARG) DIRECTOR.

Copy to :-

- The Dy. Health Officer, Central Zone, South Delhi Municipal Corporation, Jal Vihar, Lajpat
- M/s McDonald's Family Restaurant Located at BG-02, Ground floor, Ansal Plaza Shopping Arcades at Hudeo Place at Pinjra Pole, Andrewsganj New Delhi

## Conditions for the validity of Fire Safety Certificate:

- This NOC is valid for Ground floor only
- All the fire safety arrangement provided their in shall be maintained in good working conditions 2. at all times.
- Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- Any deviation with regard to the construction etc shall be verified by the concerned building
- This certificate cannot be treated in any case for regularizations of unauthorized construction.
- "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry"
- The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on www dfs Delhigovt nic in

## INSPECTION REPORT

1. Name & address of the building: M/s McDonald's Family Restaurant Located at BG-02, Ground floor, Ansal Plaza Shopping Arcades at Hudeo Place at Pinjra Pole, Andrews Ganj, New Delhi.

Type of Occupancy : Assembly "Group-D" (Restaurant)

3. Building Comprised of : Two tier basement, Ground Mezzanine Plus three upper

Floors. But restaurant is at ground floor only.

 Type of Case : Renewal

5. Details of previous NOC : F.6/DFS/MS/EH/SZ/2020/137 dated 29/09/2020

6. Fire Safety directives Letter No.: Nil

7. Date of inspection : 24/05/2023

8. Name of the Inspecting Officer: Sh. Santosh Kumar A.D.O. (S.J.)

Name and designation of Officer

from the building side : Sh. Devender Singh (Manager)

10. Year of Construction : 1991-1999

S No		prevention and fire safety U/R		uirements		Provide site			Remarks MR/NMR	
1.	Access of building			Ansal plaza FSC NoF6/DFS/MS/Mixed/2020/SZ/359 dated 11/09/2020						
		Road width	Requ				MR			
		Gate width	Requ	ired	5m		MR			
	•	Width of internal roa	ad Requ	ired	Variable Daylor	Provided as per approved plans		MR (Old case)		
2.	Number, width, Type & Arrangements of exits									
-	a. Number of staircases									
	Upper floors			NA NA		NA	NA i		ن	
	Basements			NA NA		NA	1	A		
	b.	Width of staircases								
		Upper floors		NA N		NA	N		NA	
		Basements		NA		NA.	<b>A</b> ::		NA	
	C.	Protection of exits								
		Fire check door		Required	P	rovided		M	2	
	•	Pressurization		NA	N			NA		
ŧ	d. No of continuous staircase to terrace		Required	uired 04nos.(One in Block, One in I & Two in C Blo		Block	1000	R (Old se)		
	c.	e. Width Of Corridor		NA	N	NA		N/	4	
	f. Door Size		Required 02 Exit	300	1m & 1 90 m (two exits)			R (old se)		
3.	Compartmentation									
	Fire check door			Required Provi		rovided		-	R	
		Sealing of electrical shafts			Required Provided			-	R	
		C + O 1						MR		
		Water Curtain		NA		IA.		_	A	
	Fire Dampers			NA	١	NA		N	A	
	Smoke managements System							-		
-	•		30 a/c per	hour	nour N/A				NA	
1	-	Part Action	12 a/c pe	r hour		Exhaust Fans Pro			MR	
		tinguishers	(Fue F	ghting System i	common	for more mail build	ingi			
1	Total numbers 06nd		s O6nos F		os. Provided	rovided MR				
	Types AE		ABO	C, CO <sub>2</sub> &		ABC, CO <sub>2</sub> , Water CO <sub>2</sub>		MR		
			WC		+			NAD.		
	ISI marking		Req	equired		Provided		MR		

17-

6.	First - Aid Hose Reels	is common for entire mail building)				
	Total numbers on each floor	02nos.(near	02nos.(near	MR		
		restaurant)	restaurant)	WIN		
	Length of hose reel hose	30 Mtr.	30m	MR		
	Nozzle diameter	5 mm	5mm Provided	MR		
7.	Automatic fire detection and alarming	system (Fire Fightin	System (Fire Fighting System is common for entire null building)			
	Type of detector	Smoke & Heat	Smoke & Heat	MR		
	Location of Main Panel	Ground Floor	Ground Floor	MR		
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System		n is common for entire mail building)			
	Basements     Upper Floor	NA .	NA	NA		
	opper rioor	Required	Provided	MR		
	Sprinkler above false ceiling	NA	NA	NA		
11.	Internal Hydrants	(Fire Fighting Sys	tern is common for entire mail buildin	e)		
7.1	Size of riser/down-comer	150mm	150mm	MR		
	The state of the s	23011111	13011111	IVIK		
	Number of hydrants	02nos.(near	02nos.(near	MR		
	per floor	restaurant)	restaurant)			
	Hose Box	02nos.(near	02nos.(near	MR		
		restaurant)	restaurant)			
12.	Yard Hydrants	(Fire Fighting System				
	Total number of hydrants	08nos.	08nos.	MR		
12	Hose Box	08nos.	08nos.	MR		
13.	Pumping Arrangements Ground Level	(rive righting System	in common lex cause with periods.)			
>	Discharge of main pump	Dagwined	Denvided	Tue		
>	Head of main pump	Required	Provided Provided	MR		
>	Number of main pumps	Required	The state of the s	MR		
>		Required	Provided	MR		
>	Jockey pump out put	Required	Provided	MR		
	Jockey pump head	Required	Provided	MR		
>	Standby Pump out put	Required	Provided	MR		
>	Standby Pump Head	Required	Provided	MR		
A	Auto Staring/Manual stopping	Required	Provided	MR		
_	Pump House Access	Required	Provided	MR		
•	Terrace level		Total	Lavi		
>	Discharge of pump	NA	NA	NA		
>	Head of the pump	NA	NA	NA		
>	Power supply	NA	NA	NA		
>	Auto starting of pump	NA	NA	NA		
14.	Captive water Storage for fire fighting	g (Fire Fighting Syste	m is common for entire mall building	D)		
	Underground tank capacity	4,50,000ltr	4,50,000ltr	MR		
	> Draw of connection	Required	Provided	MR		
	> Fire service inlet	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
	Overhead Tank capacity	20,000 Ltrs.	20,000ltr on AB Block			
	Overnead Lank Cabacity					



m)

		N-2)				
5	Exit Signage	Required	Provided	MR		
6.	Provision of Lifts	(Fire Fighting System is common for entire mall building)				
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	NA	NA	NA		
	<ul> <li>Pressurization of lift lobby</li> </ul>	NA	NA	NA		
	Communication in lift Car	Required	Provided	MR		
	<ul> <li>Fireman's Grounding Switch</li> </ul>	Required	Provided	MR		
	<ul><li>Lift Signage</li></ul>	Required	Provided	MR		
17.	Standby power supply	Required	DG Set Provided	MR		
18.	Refuge Area	(Fire Fighting System is common for entire stall building)				
	> Total area	NA	NA	NA		
	> Location	NA	NA	NA		
19.	Fire control room					
	Detector system panel	Required	Provided	MR		
	➤ Flow Switch Panel	NA	As Above	NA		
	> PA System Panel	Required	Provided	MR		
	➤ Battery backup	Required	Provided	MR		
	<ul> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A		
20.	. Special Fire Protection	N/A	CO <sub>2</sub> & ABC	MR		

The fire protection systems provided in the building were test checked and found functional at the time of inspection. In view of the deemed compliance of the minimum standard on fire prevention and fire safety as required under the rules the NOC issued vide letter n F.6/DFS/MS/EH/SZ/2020/137 dated 29/09/2020, renewal under rule 35 of the Delhi Fire Servic Rules 2010 is recommended.

DO(SD)

Signature of the Inspecting Officer

Name : Santosh Kumar Designation : A.D.O. (S.J.)

Type Fire

Extinguisher Provided near Electric Panel

26 51 2023

Systems for Protection of

special Risks, if any;

Senecter ( )

is promo fro

Signature Pl. 1

8/wan

18/8/55 Apportor