GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Dated: 13/06/2023

No. F6/DFS/MS/EH/SZ/2023/ 125

FIRE SAFETY CERTIFICATE

Certified that the M/s. Jubiliant Food Works Ltd. (Domino Pizza) located at First Floor, Unit No. 105, Unity Mall, Janak Puri West Metro Station, New Delhi- 110058, in a building comprised of two basements, ground plus eight upper floors & terrace but restaurant is running at 1st floor only, owned/occupied by Jubiliant Food Works Ltd. (Domino Pizza). The restaurant premises was re-inspected by the officers concerned of this department on 05.06.2023 in the presence of Ms. Malti (Manager) and found that the Management of Jubiliant Food Works Ltd. (Domino Pizza) have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and the restaurant at First floor only is fit for occupancy class Assembly (Restaurant) with effect from 13 06/2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 13 06 2023 at New Delhi by.

Director

Delhi Fire Service

Copy M/s Jubiliant Food Works Ltd. (Domino Pizza) First Floor, Unit No. 105, Unity Mall Janak Puri West Metro Station, New Delhi- 110058 in r/o Online ID No. 2023052509653.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. All the means of escapes /exits shall not be locked/bolted/blocked at any time for safe evacuation of the occupants in case of any emergency.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt nic in

INSPECTION REPORT

1. Name & address of the building : M/s. Jubiliant Food Works Ltd. (Domino Pizza) located at

First Floor, Unit No. 105, Unity Mall, Janak Puri West

Metro Station, New Delhi- 58.

2. Type of Occupancy : Assembly (Restaurant)

3. Building Composition : The said Restaurant is running at First floor of a building

comprised of two basements, ground plus eight upper floors.

4. Type of Case : New case

Details of previous NOC : N/A

6. Fire Safety directives letter No : F/DFS/MS/BP/2014/207, Dated 28.07.2014 (For whole building)

Date of inspection : 05.06.2023

8. Name of the Inspecting Officers: Vedpal Chhikara, DO (SW) & P.V. Rathee, ADO (SRD)

9. Name and designation of officers

from the building side : Ms. Malti (Manager)

10. Year of Construction : 2015.

11. Applicant's letter No. : Online application Id 2023052509653. dates

io.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per NBC part-IV/ UBBL	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	06 m	Provided	MR			
	Gate width	06m	Provided	MR			
	Width of internal road	06m	Provided	MR			
2	Number, Width, Type & Arrangement of Exits (Restaurant is at 1st Floor)						
	a. Number of staircases	-		6.0			
	Upper Floors	02	02(Near Eating House)	MR			
	Basements Width of staircases Upper Floors Basements Protection of exits Fire check door Pressurization No. of continuous staircases to terrace Width of Corridor	N/A	N/A	N/A			
				IVA			
		1.50 m each	Provided	MR			
		N/A	N/A	N/A			
		-	4				
		Required	Provided	MR \			
		Required	Provided	MR			
		Required	Provided	MR			
		1.5m	Provided	MR			
	h. Door Size	2x1.5 mts	1.5 mts each	MR			
3	Compartmentation.						
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	Required	Provided	MR			
		Required	Sealed	MR			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		Required	Provided	MR			
4	Smoke Management System.						
	Basements	30 a/c per hour		N/A			
	Upper floors	12 a/c per hour	Provided	MR			
5	Fire Extinguishers						
	Total numbers	05	Provided	MR			
	Types	CO ₂ , ABC type	Provided	MR			
	IS marking	ISI marked	Provided	MR			

		1019		1481	E				
6	First-Aid Hose Reels. (Fire Fight	ting Custom to	common for whole bu						
T, TOU	Total numbers for restaurant	tilding)	15						
	Length of hose reel hose	01 30 m	Provided		MR				
	Nozzle diameter	5 mm	Provided		MR				
7			Provided		MR				
	Automatic fire detection and alarmin building)	g system. (Fire	Fighting System is co	ommon	for whole				
	T A								
	Location of Main Panel	Required	Provided		MR				
		Required Required	Provided		MR				
	Location of Repeater Panel	Required	Provided Provided		MR				
	Alternate source of power				MR				
8	Hooters' Location	Required	Provided		MR				
	MOEFA	Required	Provided		MR				
9	Public Address System.	Required	Provided	1	MR				
10	Automatic Sprinkler System. (Fire Fi	ighting System	is common for whole	building	g)				
	• Basement	N/A	N/A		N/A				
	Entire Restaurant at 1 st floor	Required	Provided		MR				
	Sprinkler above false ceiling	Required	Provided		MR				
11	Internal Hydrants (Fire Fighting	System is com	mon for whole buildir	ng)					
	Size of riser/down-comer	150 mm	Provided		MR				
	Number of hydrants for	01	Provided		MR				
	restaurant								
12	Hose Box Vard Hydropts	01	Provided		MR				
12	Yard Hydrants. Total number of hydrants	N//							
	Hose Box	N/A N/A	N/A	_	N/A				
13		200-374	N/A common for whole b		N/A				
	Ground Level	griding System is	common for whole by	uilding)					
	Discharge of main Pump Head of Main pump	Required	2850LPM	11	MR				
		Required	90m	l N	MR				
	- Total Panys	Required	Two		/IR				
	> Jockey Pump out put	Required	280LPM	I N	/IR				
	> Jockey pump head	Required	90m		1R				
	Standby Pump out put Standby Pump Head	Required	2850LPM	-	ſR				
		Required Required	90m Provided	-	IR IR				
1 3	Auto Starting/ Manual stopping Pump House Access	Required	Provided	-	IR III				
	Terrace level	Required	Provided	M	IR				
	Discharge of pump	450 LPM	900 LPM Provided	-	m				
	Head of the pump	40 mts	Provided	M	AR R				
194	The state of the s			M	R				
-	Power Supply	Required Required	Provided Provided	M					
14	Auto Starting of pump Captive Water Storage for fire fighting			ole built	ling)				
	Underground tank capacity	Required	2,00,000Liters	Mi					
	> Draw-off connection	Required	Provided	MF	-				
	> Fire service inlet	Required	Provided	MR					
	> Access to tank	Required	Provided	MR					
	Overhead Tank capacity	20,000 lts	20,000 its	MR					
	A tw								

15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	Required	Provided	MR			
	Pressurization of Lift lobby	Required	Provided	MR			
	Communication In lift Car Fireman's Grounding Switch Lift Signage	Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area						
10	> Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19	Fire Control Room (Fire Fighting System is common for whole building)						
17	Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans	Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Provided	MR			

The fire protection systems provided in the building were test/checked at random and found satisfactory at the time of inspection.

If agreed in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the Rules, it is recommended to grant fire safety certificate under rule 35of Delhi Fire Service Act-2007 & Rules-2010.

Note: The restaurant is at 1st floor in the MLCP cum Commercial building and having common fire safety installation. The FSC of the main building has been renewed in 2022.

Accordingly, DFA is put up for approval & signature please

Signature of the Inspecting Officer Name- Vedpal Chhikara Divisional Divisional Officer (SW) Signature of the Inspecting Officer Name-P.V.Rathee Assistant Divisional Officer (SRD.)

RAND 11/23

Denetar My

put ony 2 cpy Fr

Aoy En