GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2023/239

Dated: 24/17/2023

FIRE SAFETY CERTIFICATE

Certified that the RHAAS (Restaurant) Located at Ground floor of Plot no. 15A/59, WEA, Karol Bagh, New Delhi- 110005, running at ground floor only of a building comprised of basement, ground plus three upper floors, was granted FSC vide letter No. F6/DFS/MS/EH/SZ/2020/24 dated 17.01.2020. The restaurant was re-inspected by the officers concerned of this department on 14.07.2023 in presence of Sh. Kashish (Owner) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class assembly (Restaurant) (running at ground floor only) with effect from \$4 | 07 | 2013 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 24/0 7/2023 at New Delhi by.

Director Delhi Fire Service

Online application ID; - 2023070111798 dated 06.07.2023

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : M/s. RHAAS Located at Ground floor of Plot no.

15A/59, WEA, Karol Bagh, New Delhi- 110005.

2. Type of Occupancy : Asse

3. Building Composition

: Assembly (Restaurant), At Ground Floor Only

: Said restaurant is running at Ground floor of a building comprised of basement, ground plus three upper floors.

4. Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/EH/SZ/2020/24 dated 17.01.2020

6. Fire Safety directives letter No : N/A.

7. Date of inspection : 14.07.2023

8. Name of the Inspecting Officers: Vedpal Chhikara, DO (SW) & P.V. Rathee, ADO (SRD)

9. Name and designation of officers

from the building side : Sh. Kashish (Owner)

9. Year of Construction : 2004

10. Applicant's letter No. : Online application ID 2023070111798 dated 06.07.2023

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as UBBL / NBC-IV	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	06 mts	Provided	MR			
	Gate width Width of internal road	N/A	Directly accessible from the road	N/A			
-		N/A	N/A	N/A			
2	Number, Width, Type & Arrangeme	nt of Exits					
	a. Number of staircases			E			
	Upper Floors	N/A	N/A	Restaurant running at GF only			
	Basements Width of staircases	N/A	N/A	N/A			
				-			
	Upper Floors	N/A	N/A	Restaurant running at GF only			
	Basements	N/A	N/A	Restaurant running at GF only			
	c. Protection of exits			-			
	Fire check door	N/A	N/A	N/A			
	Pressurization No. of continuous staircases t	o N/A	N/A	N/A			
	terrace	N/A	N/A	N/A			
	g. Width of Corridor	N/A	N/A	N/A			
	h. Door Size	2.0 & 1.50 m	ts. 2.0, 2.0 & .90 mts	MR			
3	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain Fire Dampers	N/A	N/A	N/A			
		N/A	N/A	N/A			
4	Smoke Management System.			-			

by he

		N-9				
	Basements	30 a/c per hour	N/A	Restaurant runnir GF only		
	ground floor	12 a/c per hour	Exhaust fan provided	MR		
	Fire Extinguishers					
	Total numbers	07	Provided	MR		
	• Types	CO ₂ , ABC type	Provided	MR		
	IS marking	ISI marked	Provided	MR		
,	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system.					
	Type of detectors	Smoke/Heat	Provided	MR		
	Location of Main Panel	Required	Provided	MR		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
10	Basement	N/A	N/A	N/A		
	Entire Restaurant	N/A	Provided	N/A		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	100 mm	Provided	MR		
	 Number of hydrants per floor 	01	Provided	MR		
	Hose Box	01	Provided	MR		
	Yard Hydrants.					
12	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	· N/A	N/A	N/A		
	Pumping Arrangements.					
13	Ground Level	,	26.11			
	TOP SOMEOMERS TO USE	N/A	N/A	N/A		
	 Discharge of main Pump 	N/A	N/A	N/A		
	- Head of Main pump	N/A	N/A	N/A		
	 Number of main pumps 	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	 Standby Pump Head 		N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	· N/A		
	Pump House Access	N/A	IN/A			
	Terrace level Nicology of pump	450 LPM	Provided	MR		
	 Discharge of pump 	130 51 111	Provided	MR		

	-		N-10			
		T	Required	Provided		
		Power Supply	Required	Provided	М.	
	Auto Starting of pump			- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		
C	Captive Water Storage for fire fighting.			N/A	N/A	
-	Underground tank capacity	N/A		N/A		
	•	Draw-off connection Fire service inlet Access to tank	N/A	N/A	N/A	
			N/A	N/A	N/A	
	1		N/A	N/A	MR	
	1		20,000 Ltrs.	Provided	MR	
1	•	Overhead Tank capacity	Required	Provided	WIK	
1	Exit	Signage.	TREG		21/4	
-		tion of Lifts.	N/A	N/A	N/A N/A	
-		Pressurization of Lift Shart Pressurization of Lift lobby Communication In lift Car	N/A	N/A		
			N/A	N/A	N/A	
			N/A	N/A	N/A	
		Fireman's Grounding Switch	N/A	N/A	N/A	
		Lift Signage	Required	Provided	MR	
7	St	Standby power supply Required				
	_	fuge Area.	A	N/A	N/A	
8	-	Total Area	N/A	N/A	N/A	
		Location	N/A	N/A		
	-			N/A	N/A	
19	F	Oetector System Panel	N/A	N/A	N/A	
		er Switch Panel	N/A	N/A	N/A	
		PA System Panel	N/A	N/A	N/A	
		Batter backup	N/A	N/A	N/A	
		Building Floor Plans	N/A	Two ABC type fire	MR	
	0	Special Fire Protection Systems for Protection of special Risks, if any:	Required	extinguisher found provided near elect, pan-	el	

The fire protection systems provided in the building were checked at random and found

In view the deemed compliance of the minimum standards on fire prevention and fire safety satisfactory at the time of inspection. measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/EH/SZ/2020/24 dated 17.01.2020 . renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly. DFA is put up for approval & signature please. - tower to hever speech

Signature of the Inspecting Officer

Name- Vedpal Chhikara Divisional Officer (SW)

Signature of the Inspecting Officer Name- P.V. Rathee Divisional Asstt. Div. Officer (S.Rd)