

c/31

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001**

No.F6/DFS/MS/School/NDZ/2023 | 679

Dated: 27/09/2023

**FIRE SAFETY CERTIFICATE**

Certified that the **Bishop Boys Diocesan School** located at **6-B, Rajpur Road, Delhi - 110054**, comprised of **Ground + Two upper floors** (only one room at 2<sup>nd</sup> floor which is used for storage only) owned/ occupied by the Bishop Boys Diocesan School was granted FSC by this department vide letter **No.F6/DFS/MS/School/2017/NDZ/803 dated 06.06.2017**. The premises was re-inspected by the officer concerned of this department on 15.09.2023 in the presence of Mrs. Monica Massy (Principal) and found that the premises/building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules 2010 and the building is fit for occupancy class (**Group-B**) "**Educational Building**" with effect from 27/09/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 27/09/2023 at New Delhi by

  
(Atul Garg)  
Director  
Delhi Fire Service o/c  
Tel: 011-23414000  
679

**Copy to:-**

1. The Director of Education,  
Govt. of NCT of Delhi, Old Secretariat, Delhi.
2. The Principal, Bishop Boys Diocesan School 6-B, Rajpur Road, Delhi - 110054.

**Conditions for the validity of Fire Safety Certificate**

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)

- N/18-  
**INSPECTION REPORT**

1	Name and address of the building:	<b>Bishop Boys Diocesan School at 6-B, Rajpur Road, Delhi - 54.</b>
2	Type of occupancy with details of floors:	<b>Educational Building Group -B</b> Ground+ 2 upper floor ( 01room at 2 <sup>nd</sup> floor which is used for storage only )
3	Type of case:	Renewal case
4	Details of previous FSC:	F6/DFS/MS/School/2017/NDZ/803 dated 06.06.2017
5	Fire safety directives no.:	NA
6	Date of inspection:	15.09.2023
7	Name of the inspecting officer:	Sumit Kumar, ADO (SPM)
8	Name and designation of the officer from the building side:	Mrs. Monica Massey (Principal)
9	Year of construction:	2002
10	Reference letter no.:	Outdoor dairy no. 5058 dated 17.08.2023

S.No	Minimum Standards on fire safety requirements as per circular no. F.16/Estate/fire safety/2011/3298-3398 dated 01.03.2011	Requirements	Provide at site	Remarks MR/NM R
1	<b>Access to Building</b>			
	A	Road width	6 mtrs.	6 mtrs. ✓ <b>MR</b>
	B	Gate width	NA	NA
	C	Width of internal roads	NA	NA
2	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	A	<b>No. of Staircase:</b>		
		a) Upper floor	02 nos.	02 nos. <b>MR</b>
		b) Basements	NA	NA
	B	<b>Width of the Staircase:</b>		
		a) Upper floor	1.5 mtrs.	1.50, & 1.40 mtrs. ✓ <b>MR</b>
		b) Basements	NA	NA
	C	<b>Protection of Exits</b>		
		a) Fire check door	NA	NA
		b) Pressurization	NA	NA
	D	No. of continuous staircase to terrace:	01 nos.	01 nos. <b>MR</b>
	F	Width of the corridor	NA	NA
	E	Door size	1.0 mtrs.	1.0 mtrs. <b>MR</b>
3	<b>Compartmentation:</b>			
	A	Fire check doors	NA	NA
	B	Sealing of electrical shafts	NA	NA
	C	Fire rating of shaft doors	NA	NA
	D	Water curtain	NA	NA
	E	Fire dampers	NA	NA
4	<b>Smoke management System:</b>			
	A	Upper floors	12 a/c per hour	NA
	B	Basements	30 a/c per hour	NA
5	<b>Fire extinguishers</b>			
	A	Total numbers	06 nos.	06 nos. <b>MR</b>
	B	Types	CO2 , ABC	CO2, ABC <b>MR</b>
	C	ISI marking	Required	Provided <b>MR</b>

84

60

-N/19-

<b>6</b>	<b>First Aid Hose reel</b>				
	<b>A</b>	Total no. at each floor	1 nos.	1 nos.	<b>MR</b>
	<b>B</b>	Length of Hose Reel	30 m	30 m	<b>MR</b>
	<b>C</b>	Nozzle diameter	5 mm	5 mm	<b>MR</b>
<b>7</b>	<b>Automatic Fire Detection and Alarm System (ADAS)</b>				
	<b>A</b>	Type of Detectors	NA	NA	NA
	<b>B</b>	Location of main Panel	NA	NA	NA
	<b>C</b>	Location of Repeater Panel	NA	NA	NA
	<b>D</b>	Alternate power Source	NA	NA	NA
	<b>E</b>	Hooter's location	NA	NA	NA
<b>8</b>	<b>MOEFA</b>		NA	NA	NA
<b>9</b>	<b>Public Address System</b>		NA	NA	NA
<b>10</b>	<b>Automatic Sprinkler System</b>				
	<b>A</b>	Basement	NA	NA	NA
	<b>B</b>	Upper Floor	NA	NA	NA
	<b>C</b>	Sprinklers above false ceiling	NA	NA	NA
<b>11</b>	<b>Internal hydrants</b>				
	<b>A</b>	Size of the riser/down comer	NA	NA	NA
	<b>B</b>	No. Of hydrants per floor	NA	NA	NA
	<b>C</b>	Hose box	NA	NA	NA
<b>12</b>	<b>Yard Hydrants</b>				
	<b>A</b>	Total no. of hydrants	NA	NA	NA
	<b>B</b>	Hose box	NA	NA	NA
<b>13</b>	<b>Pumping arrangements</b>				
	<b>A</b>	Ground Level			
		a) Discharge of main pump	NA	NA	NA
		b) Head of main pump	NA	NA	NA
		c) Number of main pump	NA	NA	NA
		d) Discharge of jockey pump	NA	NA	NA
		e) Head of jockey pump	NA	NA	NA
		f) Discharge of Standby pump	NA	NA	NA
		g) Head of Standby pump	NA	NA	NA
		h) Auto starting/ manual stopping	NA	NA	NA
	<b>B</b>	Terrace Level			
		a) Discharge of terrace pump	450 LPM	450 LPM	<b>MR</b>
		b) Head of terrace pump	40 mtrs.	40 mtrs.	<b>MR</b>
		c) Alternate power supply	Required	Provided	<b>MR</b>
		d) Auto starting of pump	Required	Provided	<b>MR</b>
<b>14</b>	<b>Captive Water Storage for Fire Fighting</b>				
	<b>A</b>	Underground tank capacity	NA	NA	NA
	<b>B</b>	Draw off connection	NA	NA	NA
	<b>C</b>	Fire Service Inlet	NA	NA	NA
	<b>E</b>	Access to tank	NA	NA	NA
	<b>D</b>	Overhead tank capacity	10,000 Ltrs.	10,000 Ltrs.	<b>MR</b>
<b>15</b>	<b>Exit Signage</b>		Required	Provided	<b>MR</b>
<b>16</b>	<b>Provision of lift</b>				
	<b>A</b>	Pressurization of lift shaft	NA	NA	NA
	<b>B</b>	Pressurization of lift lobby	NA	NA	NA
	<b>C</b>	Communication in lift car	NA	NA	NA
	<b>D</b>	Fireman switch	NA	NA	NA
	<b>E</b>	Lift signage	NA	NA	NA
<b>17</b>	<b>Standby Power Supply</b>		NA	NA	NA

82

81

80


-1/20

<b>18</b>	<b>Refuge Area</b>			
A	location	NA	NA	NA
B	Total area	NA	NA	NA
<b>19</b>	<b>Fire Control Room</b>			
A	Fire Detection System panel	NA	NA	NA
B	Flow switch panel	NA	NA	NA
C	P A system panel	NA	NA	NA
D	Battery backup	NA	NA	NA
E	Building floor plan	NA	NA	NA
<b>20</b>	<b>Special Fire Protection for special risk if any</b>			

The fire protection systems provided in the school were tested, checked at random found functional at the time of inspection.


Shortcomings communicated vide letter No.F6/DFS/MS/School/NDZ/2021/559 dated 11.10.2021 has been rectified.


In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required as per Director Education, Circular FSC issued vide letter in. F6/DFS/MS/School/2017/NDZ/803 dated 06.06.2017, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.


  
 Signature of the Inspecting Officer  
 Name Sumit Kumar  
 Designation ADO (SPM)


DO (OD)

  
26/9/23

  
Dy. C.F.O. (002)


  
21/09/23


  
C.F.O. 21/9/2023

  
Director 21/9/23

  
ADY SPM

F.T. letter is put up for signature, please

  
25/09/2023

  
Director (DFS)