## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2023/WZ/EH/342

Dated: 20/11/2023

## FIRE SAFETY CERTIFICATE

Issued on ... 20 11 1 2023 .... at New Delhi by

(Arul Garg) DIRECTOR Ph; 011-23414000

Copy to: -

1. MHA Id- 2023102317656 dated 24.10.2023

Conditions for the validity of Fire Safety Certificate:

 All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- All the means of escape shall be kept free of any obstruction all the time to evacuate the
  occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Fire+Safety+Acts+and+Rules http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

8/11/2

	•						
PAT I	in the second	INSPECTION REPORT					
1.	Name	& address of the building					
2.	Туре	e of Occupancy Group D Assembly Build			AA Night Club	running at	
	2011	The American Company	Ground	floor only)	21/11/25		
		of Case	Renewal				
		s of Previous NOC		/MS/2020/WZ/159 dated 1	3.11.2020.	printer i	
		afety directives letter No	-NA-				
		of Inspection	01.11.2023 Sh. Ajay Kumar Sharma (ADO Rohini)			100	
			adev (Manager)				
		the building side		And the state of t	- 10	AND AND ADDRESS OF THE PARTY OF	
9. Year of Construction 2015		104 10 2022					
		pplication No.2023102317656 dated 24.10.2023.    RRI /NRC   Provided at   Remarks					
S. No.		nimum Standards on fire profire safety U/R 33		BBL/NBC Requiring	site	MR/NMR	
1.		ess to building [M DFS/MS/2018/1398 dated 13/0		Paradise Mall has been	issued FSC vid		
	Road width			Restaurant with in Mall	As per mall	MR	
	111-1	Gate width		Restaurant with in Mall	As per mall	MR	
	Width of internal road		Restaurant with in Mall	As per mall	MR		
2.	Nu	nber, Width, Type & Arran	gement of	Exits			
-	d. Number of staircases		47				
	Upper Floors			-NA-	-NA-	-NA-	
	Basements		-NA-	-NA-	-NA-		
	e. V	e. Width of staircases			- water		
	Upper Floor		-NA-	-NA-	-NA-		
		Basements		-NA-	-NA-	-NA-	
	f. I	Protection of exits	1 1 1	SIL MARKET MARKET	mittall fluit		
		Fire check door		-NA-	-NA-	-NA-	
		<ul> <li>Pressurization</li> </ul>		-NA-	-NA-	-NA-	
	d. N	No. of continuous staircases to terrace		-NA-	-NA-	-NA-	
	e. W	Width of Corridor		-NA-	-NA-	-NA-	
	f. D	Door Size		1.5m & 2m	Provided	MR	
	Compartmentation			Restaurant with in Mall	As above	MR	
	Fire check door			-NA-	-NA-	-NA-	
		Sealing of electrical shafts		-NA-	-NA-	-NA-	
	•		ulter san	-NA-	-NA-	-NA-	
		Water Curtain		-NA-	-NA-	-NA-	
	•	Fire Dampers		-NA-	-NA-	-NA-	
	Smoke Management System						
	Basements			Restaurant with in Mall	As per mall	MR	
	Upper floors		Restaurant with in Mall	As per mall	MR		
5.	Fire Extinguishers						
	Total numbers			04nos.	04nos.	MR	
	Types			ABC/CO2	ABC-3/CO2-1	MR	
	IS marking			ISI marked	Yes	MR	
X.	First-Aid Hose Reels						
	•	Total numbers on each floor		Required	As per mall	MR	
	Length of hose reel hose		30mm	As per mall	MR		

My

1

				7			
	Nozzle diameter	5m	As per mall	MR			
7.	Automatic fire detection and alarming	system		- III			
- 44	Type of detectors	Required	Provided	MR			
	Location of Main Panel	Restaurant with in Mall	As per mall	MR			
	Location of Repeater Panel	Restaurant with in Mall	As per mall	MR			
	Alternate source of power	Required	Provided	MR			
8.	Hooters' Location	Required	Provided	MR			
9.	MOEFA Public Address System	Required	Provided	MR			
10.	Public Address System Automatic Sprinkler System	Restaurant with in Mall	As per mall	MR			
10.	Basement	-NA-	-NA-	-NA-			
	Ground & Upper Floors	Required	Provided				
	Sprinkler above false ceiling		120 CONTRACTOR CO.	MR			
11.	Internal Hydrants	Restaurant with in Mall	As above	MR			
11.	Size of riser/down-comer	Restaurant with in Mall	A a man mall	MR			
		Service and the service and th	As per mall				
	Number of hydrants per floor     Hose Box	Restaurant with in Mall	As per mall	MR			
12		Restaurant with in Mall	As per mall	MR			
12.	Yard Hydrants	Destaura del Care de		) m			
	Total number of hydrants	Restaurant with in Mall	As per mall	MR			
	Hose Box	Restaurant with in Mall	As per mall	MR			
13.	Pumping Arrangements	15 33 34 0		1.0			
	Ground Level	Restaurant with in Mall	As per mall	MR			
	Discharge of main Pump	Restaurant with in Mall	As per mall	MR			
	> Head of Main pump	Restaurant with in Mall	As per mall	MR			
	> Number of main pumps	Restaurant with in Mall	As per mall	MR			
	> Jockey Pump out put	Restaurant with in Mall	As per mall	MR			
	> Jockey pump head	Restaurant with in Mall	As per mall	MR			
	> Standby Pump out put	Restaurant with in Mall	As per mall	MR			
	➤ Standby Pump Head	Restaurant with in Mall	As per mall	MR			
	> Auto Starting/Manual Stopping	Restaurant with in Mall	As per mall	MR			
	> Pump House Access	Restaurant with in Mall	As per mall	MR			
	Terrace level	No.	LATE PRINTER				
	Discharge of pump	Restaurant with in Mall	As per mall	MR			
	➤ Head of the pump	Restaurant with in Mall	As per mall	MR			
	➤ Power Supply	Restaurant with in Mall	As per mall	MR			
	> Auto Starting of pump	Restaurant with in Mall	As per mall	MR			
4.	Captive Water Storage for fire fighting						
	Underground tank capacity	Restaurant with in Mall	As per mall	MR			
	> Draw-off connection	Restaurant with in Mall	As per mall	MR			
		ACED AND DESCRIPTION OF THE PROPERTY OF THE PR					
	> Fire service inlet	Restaurant with in Mall	As per mall	MR			
	Access to tank	Restaurant with in Mall	As per mall	MR			
-	Overhead Tank capacity	Restaurant with in Mall	As per mall	MR			
5.	Exit Signage.	Required	Provided	MR			
6.	Provision of Lifts.						
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-			
	Pressurization of Lift lobby	-NA-	-NA-				
	Communication In lift Car			-NA-			
		-NA-	-NA-	-NA-			
	Fireman's Grounding Switch	-NA-	-NA-	-NA-			
	Lift Signage	-NA-	-NA-	-NA-			
7.	Standby power supply	Restaurant with in Mall	As per mall	MR			

1		NIG		
1		, , , ,		
M	. )			
12/	6			
1.	Refuge Area.	-NA-	-NA-	-NA-
AF	Total Area	-NA-	-NA-	-NA-
	Location			
19.	Fire Control Room	-NA-	-NA-	-NA-
	Detector System Panel	-NA-	-NA-	-NA-
	Flow Switch Panel	-NA-	-NA-	-NA-
	PA System Panel	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA- ·
	Building Floor Plans	-NA-	-NA-	-NA-
0.	Special Fire Protection System for			domly and
	Protection of special Risks, if any:  Accordingly, the fire protection systems pro	vided in the building we	re tested/ checked i	randomly and
	Keeping in view the satisfactory co and fire safety required as stipulated in NBC no. 587 dated 30.10.2023, the FSC issu 13.11.2020, renewal under rule 37 of the D	ed vide letter no. F.G elhi Fire Service Rules,	2010 is recommend	ied
		Si N	gnature of the Insp ame Ajay K	ecting Officer Sumar Sharma ADO(Rohini)
600 10/1	Director Mush 10/11/2  Director My 13/11  Fi letter to me and signature	f up for	she for	mal
	Diviety Diviety		no order	17/11/23