

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/ 376

Dated: 27/12 /2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Chilis Grill & Bar Situated at Shop No 161A, Ground Floor, DLF Avenue Mall, Saket New Delhi -110017 in the building comprised of 03 tiers Basement, Ground plus Seven Upper floors owned/occupied by Unit of Paramount Restaurant Pvt Ltd was issued FSC by this department vide letter F6/DFS/MS/EH/SZ/2021/12 dated 12/01/2021. The restaurant premise was re-inspected by the officers concerned of this department on 20/12/2023 in the presence of Sh. Rajiv Singh and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class-D "Assembly Building" and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 27/12/2023 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer (MCD), Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID 2023112718935 dated 27/11/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire-fighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."





	Name & Address of d	ION REPORT	personal management			
	Name & Address of the Building		Bar Restaurant (Unit o	f Paramoun		
		Restaurant Pvt Ltd	D at Shop No. 161A G	round Floor		
2	Type of Occupancy	Restaurant Pvt Ltd) at Shop No 161A, Ground Floo DLF Avenue Mall, Saket New Delhi -110017				
3	Building Comprised of	(Restaurant is running at Ground floor only)				
4	Type of Case	03 tier Resements Ground 1 07 I I - Pl				
5	JPC UI (Bee	03 tier Basements, Ground + 07 Upper Floors Renewal				
6	Details of Previous NOC		F6/DFS/MS/EH/SZ/2021/12 dated 12/01/2021			
•	Fire Safety Directives Letter No					
7	Det Co	DLF Place Mall,- F.6/MS/DFS/BP/2005/2073 dated 04/10/2005 & F.6/MS/DFS/BP/2019/135 dated 01/04/2019				
8	Date of Inspection	20/12/2023				
9	Name of the Inspecting Officers) (PCD)			
9	The of Designation of Core	DO (South) & ADO (BCP) Sh. Rajiv Singh				
	Total tile building side	Sii. Kajiv Singn				
10	Year of construction	2005				
11	Applicant letter No.	2005				
S.	Minimum standards on Fire Prevention	MHA Portal ID 2023112718935 dated 27/11/2023				
No.	and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	MR/NM		
1	Access to Building. (DLF Aver	The state of the s	5/2022/Mall/SZ/266 Dt. 15	5/06/2022)		
	Road width	12 m	Provided*	MR		
	Gate width	7m	Provided*	MR		
02	• Width of internal road	6m	Provided*	MR		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase	Provided & N	Maintained by DLF Place	, Saket		
	Upper floors.	02 Nos	16 Nos Provided*	MR		
	Basement floor.	N/A	N/A	N/A		
	b) Width of Staircase	Provided & N	Maintained by DLF Place	, Saket		
	Upper floors Basement floor	1.50 mtr & 2m	9 x 1.50m & 7 x 2m	MR		
	c) Protection of exits	N/A	N/A	N/A		
	Fire check door	Restt within Mall	Maintained by DLF Place			
	Pressurization	Restt within Mall	Provided*	MR		
	d) No. of continuous staircase to terrace	Restt within Mall	Provided* -NA-	MR		
	e) Width of corridor	N/A	N/A	MR N/A		
	f) Door size			MR		
		02 Nos	2 m & 1.31 m	(old Case		
3	Compartmentation.	Provided & N	Maintained by DLF Place	, Saket		
	Fire check door.	Restt within Mall	Provided*	MR		
	Sealing of electrical shafts.	Restt within Mall	Provided*	MR		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
4	Fire dampers.	N/A	N/A	N/A		
-4	Smoke Management system. Basement	Provided & N	Maintained by DLF Place			
	Upper floors	30 ACPH	N/A	N/A		
5	Fire Extinguishers.	12 ACPH	Exhaust Fans Provided	MR		
-	Total numbers	Required	00).			
	Types	ABC/CO ₂	08 Nos ABC & CO ₂	MR		
	ISI Marking	Required	Provided	MR		
6	First Aid Hose Reels.		Maintained by DLF Place	MR		
	Total numbers on each floor.	One near Restt	Provided*	MR		
	 Length of hose-reel hose. 	30m	Provided*	MR		
	Nozzle Diameter	5mm	Provided*	MR		
7	Automatic fire detection & alarming system		aintained by DLF Place,	Saket		
	Type of detectors	Required	Smoke & heat	MR		
			A CONTRACTOR CONTRACTOR			
	Location of Main Panel	Required	Provided*	MD		
	Location of Main Panel Location of Repeater Panel Alternate source of power	Required Required	Provided* Provided*	MR MR		







	- Washington	T -		5	
8	Hooter's location MOEFA	Required	Provided*	MR	
9	Public Address System	Required	Provided	MR	
10	Automatic Sprinkler System	N/A	As above	MR	
10	Basement		aintained by DLF Plac	e, Saket	
		Required	Provided*	MR	
	Ground floor.	Required	Provided*	MR	
11	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants.	Provided & Maintained by DLF Place, Saket			
	Size of Riser/Down-comer	Required	Provided*	MR	
	Number of Hydrant per floor	One near Restt	Provided*	MR	
••	Hose box.	One near Restt	Provided*	MR	
12	Yard Hydrants.		laintained by DLF Plac	e, Saket	
	 Total number of hydrants. 	N/A	As above	N/A	
	Hose box.	N/A	As above	N/A	
13	Pumping arrangements.		faintained by DLF Plac		
	Ground Level	Common pumping arrangements for entire bldg			
	Discharge of main pump.	4500 LPM	4500 LPM	MR	
	Head of main pump.	70m	70m	MR	
	Number of main pumps.	02 Nos.	02 Nos.	MR	
	> Jockey Pump output.	180 LPM	180 LPM	MR	
	Jockey Pump head.	70m	70m	MR	
	Standby Pump output.	4500 LPM	2 X 4500 LPM	MR	
	Standby Pump head.	70m	70m	MR	
	Auto Starting/Manual Stopping.	Required	Provided	MR	
	Pump house access.	Required	Provided	MR	
	Terrace Level				
	Discharge of pump.	450 LPM	Provided*	MR	
	> Head of pump.	40 m	Provided*	MR	
	Power supply.	Required	Provided*	MR	
	> Auto starting of pump.	Required	Provided*	MR	
14	Captive water storage for fire fighting.	Provided & Maintained by DLF Place, Saket			
	 Underground tank capacity. 	Required	3,70,000 Ltrs	MR	
	Draw-off connection.	Required	Provided	MR	
	Fire Service Inlet.	Required	Provided	MR	
	Access to tank.	Required	Provided	MR	
	Overhead tank capacity.	Required	30,000 Ltrs	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.	Provided & Maintained by DLF Place, Saket			
	Pressurization of lift shaft.	Required	Provided*	MR	
	 Pressurization of lift lobby. 	Required	Provided*	MR	
	 Communication in lift car. 	Required	Provided*	MR	
	Fireman's switch.	Required	Provided*	MR	
	Lift signage.	Required	Provided*	MR	
17	Standby Power Supply	Required	Provided	MR	
18	Refuge Area	Openity to the Control of Maria		- wite	
	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
19	Fire Control Room.	50,025.77	faintained by DLF Place		
	Detector system panel.	N/A	Provided*	N/A	
	Flow switch panel.	N/A	Provided*	N/A	
	PA system panel.	N/A	Provided*	N/A	
	Battery backup.	N/A	Provided*	N/A	
20	Building floor plan.	N/A			
	Danielle Hoor Pium.	1071	Provided*	N/A	



Protection of special Risk, if any.

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2021/12 dated 12/01/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO(HQ)

Horl BCD

