GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**

No F6/DFS/MS/2024/EH/WZ/ 2.5

Dated : 25/01/2024

FIRE SAFETY CERTIFICATE

Certified that the KFC Restaurant, (M/s Sapphire Food India Pvt. Ltd), Unit No.17, Ground floor located at Unity one Mall, Metro Station City, Sector-10, Rohini, Delhi-110085, is running at in a mall ground floor in a mall building comprised of Basement + Ground + 6 upper floors has already been issued FSC by this department vide letter No F.6/DFS/MS/2020/WZ/01 dated 01.01.2021. The premises was re-inspected by the officer concerned of this department on 17.01.2024 in the presence of Mrs. Narender (RGM) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Group D "Assembly" (Eating House) for Unit No.G-17, ground floor only with effect from 25 01 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 25/01/2024 at New Delhi by

Ph: 011-23414000

Copy to:-

MHA Portal ID.2024010100001 dated 01.01.2024

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first

schedule of Delhi Fire Service Rules 2010. The form is available on

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

_	0		INSP	ECTION REPORT			
<u>_</u>		6 - 11 C41 - 1 - 1111					
1.	Nam	e & address of the building	No.1	KFC Restaurant, (M/s S 7, Ground floor located Sector-10, Rohini, Delhi	at Unity one Ma	a Pvt. Ltd), Un Ill, Metro Statio	
2.		of Occupancy		p D Assembly Building (
3.	Туре	of Case	Rene	wal (Restaurant is rur nd floor)		at Unit No.G-1	
4.		ls of Previous NOC		FS/MS/2020/WZ/01 date	ed 01.01.2021		
5.	Fire	Safety directives letter No	1000	FS/MS/BP/2014/50 dated .2019.	d 06.02.2014 & Ev	en No.2101 dated	
6.		of inspection	17.01				
	2000	e of Inspecting Officer	Sh. A	jay Kumar Sharma (ADC	Rohini)	NAME OF	
8.	Nam From	e and designation of officers the building side	Mr. N	larender (RGM)	and the state of	Company (A)	
9.	Year	of Construction	2015				
10.	Appl	cant's letter No.	Onlin	e application No.2024010	100001 dated 01.0	1.2024	
S. No	Mini	mum Standards on fire prev fire safety U/R 33	ention	UBBL/NBC Restaurant	Provided at site	Remarks MR/NMR	
1.		ss to building	one multi level car parking cum commercial complex issued ide letter No.F.6/DFS/MS/2022/454 dated 12.10.2022.				
-		Road width		Restaurant within mall		-NA-	
		Gate width		Restaurant within mall	As above	-NA-	
- 1		Width of internal road		Restaurant within mall	As above	-NA-	
2.	Num	ber, Width, Type & Arrange	ment of	Exits [Provided & Mai	ntained by Mall N	[anagement]	
-		mber of staircases		100			
F		Upper Floors		Restaurant within mall	As above	-NA-	
- 1	-	Basements		Restaurant within mall	As above	-NA-	
h	. W	dth of staircases		- 1			
- F		Upper Floor		Restaurant within mall	As above	-NA-	
H		Basements		Restaurant within mall	As above	-NA-	
-	P	otection of exits		JUL 19	Maria Ivani		
F		Fire check door		Restaurant within mall	As above	-NA-	
-	-	Pressurization		Restaurant within mall	As above	-NA-	
1	No	of continuous staircases to t	errace	Restaurant within mall	As above	-NA-	
e.		dth of Corridor		Restaurant within mall	As above	-NA-	
f.		or Size		2.0m & 1.5mtr	2.0m & 1.5m	MR	
. (Comp	artmentation			Describe the second	-NA-	
	•	Fire check door		Restaurant within mall	As above	-NA-	
		Sealing of electrical shafts	11	Restaurant within mall	As above	-NA-	
1	•	Fire Rating of shaft door	4	Restaurant within mall	As above	-NA-	
	•	Water Curtain		Restaurant within mall	As above	-NA-	
	•	Fire Dampers		Restaurant within mall	As above		
. 5	Smoke	Management System		[Provided & Maintained by Mall Management]			
	a)	Basements		-NA-	-NA-		
1	b)	Upper floors		12 a/c per hour	Natural ventilated	IVIK	
. 1	Fire E	xtinguishers			0.5	MR	
	•	Total numbers		05nos.	05nos.	MR	
	•	Types		ABC/CO2	ABC/CO2	MR	
	•	IS marking		ISI marked	Yes		
. 1		Aid Hose Reels		[Provided & Maintain	ed by Mall Mana	gement	

Chy

4

M	12
1,	112

. Fire

				M		
	Total numbers on each floor	01(Near to Restaurant)	As above	MR		
. }	Length of hose reel hose	30mm	As above	MR		
1	Nozzle diameter	5m	As above	-ogement]		
7.	Automotic fire detection and clarming system [Provided & Maintained by Mail I					
	a) Type of detectors	Required	Flovidor	-NA-		
	b) Location of Main Panel	-NA-	As above	-NA-		
ŀ	c) Location of Repeater Panel	-NA-	As above	-NA-		
	d) Alternate source of power	-NA-	As above	-NA-		
	e) Hooters' Location	-NA-	As above	_U		
3.	MOEFA	Required	Provided	MR		
).	Public Address System	NIA	As above	-NA-		
0.	Automatic Sprinkler System	[Provided & Maintai	ned by Mall Man	agement		
247,61	Basement	-NA-	As above	-1172		
	Ground & Upper Floors	-NA-	As above	-NA-		
	Sprinkler above false ceiling	-NA-	As above	-NA-		
11.	Internal Hydrants	[Provided & Maintai	ned by Mall Man	agement]		
•••	Size of riser/down-comer	100mm	As above	MR		
-	Number of hydrants per floor	01(Near to Restaurant)	As above	MR		
	Hose Box	01(Near to Restaurant)	As above	MR		
12.	Yard Hydrants					
12.	Total number of hydrants	-NA-	-NA-	-NA-		
	eyester construction and a street end of the construction	-NA-	-NA-	-NA-		
fex	• Hose Box					
13.	Pumping Arrangements Ground Level	-NA-	-NA-	-NA-		
5		-NA-	-NA-	-NA-		
	 Discharge of main Pump Head of Main pump 	-NA-	-NA-	-NA-		
	 Number of main pumps 	-NA-	-NA-	-NA-		
	> Jockey Pump out put	-NA-	-NA-	-NA-		
	> Jockey pump head	-NA-	-NA-	-NA-		
	> Standby Pump out put	-NA-	-NA-	-NA-		
	Standby Pump Head	-NA-	-NA-	-NA-		
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-		
	> Pump House Access	-NA-	-NA-	-NA-		
		[Provided & Maintai	CHANGE PO			
	Terrace level	Action of the Charles and a second of the Charles and	As above	4 .		
	> Discharge of pump	-NA-		-NA-		
	> Head of the pump	-NA-	As above	-NA-		
	> Power Supply	Required	As above	MR		
14.	Auto Starting of pump	Required 8 Mainta	As above	MR		
14.						
	Underground tank capacity	-NA-	As above	-NA-		
	> Draw-off connection	-NA-	As above	-NA-		
	> Fire service inlet	-NA-	As above	-NA-		
	> Access to tank	-NA-	As above	-NA-		
	Overhead Tank capacity	-NA-	As above	-NA-		
15		Required	Provided	MR		
16	. Provision of Lifts.			IVIIC		
		1				
	 Pressurization of Lift Shaft 	-NA-	As above	-NA-		

	2				
è	• Communication In lift Car	-NA-	As above	-NA-	
V	• Fireman's Grounding Switch	-NA-	As above	-NA-	
1	• Lift Signage	-NA-	As above	-NA-	
1	Standby power supply	Required	As above	10.00	
1	Refuge Area.	[Provided & Maintained by Mall Management]			
I	> Total Area	-NA-	As above	-NA-	
	> Location	-NA-	As above	(3) (3) (4)	
	Fire Control Room	Provided & Maintained by Mall Management			
	Detector System Panel	-NA-	As above	-NA-	
	Flow Switch Panel	-NA-	As above	-NA-	
	PA System Panel	-NA-	As above	-NA-	
	Battery backup	-NA-	As above	-NA-	
	Building Floor Plans	-NA-	As above	-NA-	
	Special Fire Protection System for Protection of special Risks, if any:	-NA-	As above	-NA-	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2020/WZ/01 dated 01.01.2021 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Name Ajay Kumar Sharma Designation ADO(Rohini)

DY/CFO(WZ)