061

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/EH/2024/SZ/ 128

Dated: 07/05/202

FIRE SAFETY CERTIFICATE

Certified that the M/s IKK Punjab (A unit of Superlicious Foodworks LLP) at J-2/17, B.K. Dutt Market, Rajouri Garden, New Delhi-110027, comprised of basement, ground floor plus three upper floors but the restaurant is running at ground floor and first upper floor only. The FSC was issued vide letter No. F6/DFS/MS/EH/2021/SZ/128 Dated 12.07.2021, owned/occupied by M/s IKK Punjab (A unit of Superlicious Foodworks LLP). The restaurant was re-inspected by the officer concerned of this department on 26.04.2024 in the presence of Sh. Pawan (Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Ground floor plus one upper floor) is fit for occupancy class Group D "Assembly Building" w.e.f. Offo5/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed Below.

Issued on 0.7105 2024 at New Delhi.

Director Delhi Fire Service

Online application ID 2022070814258 dated 12.04.2024

Following fire safety directives must be adhered to: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. Basement shall be used as per the building bye laws.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

Name & address of the building:

M/s IKK Punjab (a unit of Superlicious Foodworks LLP), J-2/17,

B.K. Dutt Market, Rajouri Garden, New Delhi-110027.

Type of Occupancy

Group D (Assembly Building)

Building Comprised of

basement, ground plus three upper floors but restaurant is running at

ground and first floor only. Basement is closed by gypsum board

Type of Case

Renewal

5. Details of Previous NOC

F6/DFS/MS/EH/2021/SZ/128 Dated 12.07.2021

6. Fire Safety directives letter No :

N/A

7. Date of inspection

26.04.2024

8. Name of Inspecting Officers

: A.D.O. R.K.Yadav

9. Name and designation of officers

From the building side

Sh. Pawan (Manager)

S. No.	Minimum Standards on fire prevention a fire safety U/R 33	nd UBBL-16/NBC Requirement	Provided at site	Remarks MR/NMR		
	Access to building		14.5.2 Square			
	 Road width Gate width Width of internal road 	Accessible (09 mtrs) 4.5 mtrs N/A	Provided Directly accessible from road N/A	MR MR N/A		
2.	Number, Width, Type & Arrangement of Ex	its	(restaurant is running at GF & FF			
	a. Number of staircases Upper Floors Basements	02 No.'s N/A	02 No.'s N/A	MR N/A		
	b. Width of staircases	1.5 m & 01 m	Provided	MR		
	Upper FloorBasements	N/A	N/A	N/A		
	c. Protection of exits • Fire check door	N/A N/A	N/A N/A	N/A N/A		
	Pressurization d. No. of continuous staircases to	Required	One Oncering in hall	MR MR		
	terrace e. Width of Corridor f. Door Size	1.5 m 02 m & 01 m	Opening in hall 2.08 & 1.0M	MR		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System	Required	Provided	MR		
	Basements	Required	Natural Ventilation	MR		
5.	Upper floors Fire Extinguishers	2007				
J.	Total numbers	05 No.'s	Provided	MR		
		ABC/ CO ₂	Provided	MR		
	TypesIS marking	ISI marked	ISI marked	MR		
6.	First-Aid Hose Reels		D	MD		
	Total numbers on each floor	One	Provided	MR		
n	• Length of hose reel hose • Nozzle diameter	30 mtrs 5 mm	Provided Provided	MR MR		

· /	
	19
-	V
	4

7.	Automatic fire detection and alarming system			
•	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
	MOEFA	Required	Provided	MR
	Public Address System	N/A	N/A	N/A
				37.0000
•	Automatic Sprinkler System	N/A	N/A	N/A
	Basement	N/A	N/A	N/A
	Ground Floor & Upper floor State of the conting	N/A	N/A	N/A
	Sprinkler above false ceiling			
	Internal Hydrants			
_	Size of riser/down-comer	100 mm	Provided	MR
	Number of hydrants	01 No.	Provided	MR
	Number of nydrams Hose Box	01 No.	Provided	MR
			7.1	
•	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants	N/A	N/A	N/A
	Hose Box			
	Pumping Arrangements	in the second		
-	Ground Level			N/A
	Discharge of main Pump	N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
. "	> Jockey pump head	N/A	N/A	N/A
) Joekey Parry	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	17/11		
		N/A	N/A	N/A
	> Pump House Access	**************************************		
	Terrace level	450 LPM	Provided	MF
	Discharge of pump	40 mtrs	Provided	MF
	> Head of the pump	Required	Provided	MF
	Power SupplyAuto Starting of pump	Required	Provided	MF
	7 Auto Starting of Parity	**************************************		
14.	Captive Water Storage for fire fighting			
_	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	Required	Provided	MR
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	20000 ltrs	Provided	MR
5.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.	***		(No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift Shart Pressurization of Lift lobby	N/A		
	Communication In lift Car	N/A N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage		N/A	N/A
17.		N/A	N/A	N/A
1/.	Standby power supply	Required	Provided	MR

18.	Refuge A	rea.				
		otal Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A		
19.	Fire Control Room					
	• 1	Detector System Panel	N/A	N/A	N/A	
	• 1	low Switch Panel	N/A	N/A	N/A	
	• 1	A System Panel	N/A	N/A	N/A	
	•	Battery backup	N/A	N/A	N/A	
	•	Building Floor Plans	N/A	N/A	N/A	
20.		Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC was issued vide letter no. F6/DFS/MS/EH/2021/SZ/128 Dated 12.07.2021, renewal under the rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:-Asstt. Divisional Officer

DO (South West)

30/4/M

30 41 30m

100/24

A-ON OKI

FT heller as put up for sognature please

DEPORY