



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

F.6/DFS/MS/GH/2024/SZ/137 No.

Dated: 10 /05 /2024

FIRE SAFETY CERTIFICATE

Certified that M/s T Lounge Restaurant (Devaryaa Hospitalities Pvt. Ltd.), Level-5, Terminal-3, Domestic Wing, IGI Airport, New Delhi-110037, comprised of Two-Tier Basement, Ground & Five Upper Floors but the restaurant running at 5th Floor (Domestic Wing) only, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/SZ/2021/204 dated 31/08/2021. The said premise was re-inspected by the officers concerned of this department on 03/05/2024 in the presence of Mr. Satish (Asst. Manager) and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "Assembly Group D" for a period up to 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service Rules, 2010.

Issued on 10 05 2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Joint Commissioner of Police (Lic.), 1st Floor, Police Station Defence Colony, New Delhi-110049 (w.r.t. MHA ID No. 2024041605272 dated 16/04/2024)

2. Authorized Signatory M/s T Lounge Restaurant (Devaryaa Hospitalities Pvt. Ltd.), Level-5, Terminal-3, Domestic Wing, IGI Airport, New Delhi-110037

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction. 1.

- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety 2. measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of firefighting system.
- The owner/occupier shall submit a declaration every year in form "K" provided in the first 3. schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in 4.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any. 5.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its 6. expiry".

M- :

T	Nome % 11	ON REPORT		italities		
	Name & address of the building	T Lounge Restaurant (Devaryaa Hospitalities Pvt. Ltd.), Level-5, Terminal-3, Domestic Wing, IGI Airport, New Delhi-110037				
	Type of Occupancy	Assembly Group D				
	Building Comprised of	Two Tier Resement Ground & 5 Upper Floors				
_		but the restaurant is running at 5th Floor only.				
	Type of Case	Renewal				
	Details of previous NOC	F6/DFS/MS/SZ/2021/204 dated 31/08/2021				
	Fire Safety directives letter No.	F6/DFS/MS/2007/1781 dated 05/07/2007				
	LE CONTROL CON	03/05/2024				
	Name of Inspecting Officer	Manoj Kumar Sharma (DO/SD) &				
		Santosh Kumar (ADO/SJ)				
9.	Name and designation of Officer	Sh. Satish (Asst. Manager)				
	from building side		ALM N. P. A.			
0.	Year of Construction	2010				
1.	Applicant letter No.		MHA ID No. 2024041605272 dated 16/04/2024 Provided at site Remarks			
S.	Minimum standards on fire	Old FSC	Provided at site	MR/NMR		
lo.	prevention and fire safety U/R 33	Requirements	/MS/SZ/2023/602 dated			
1.		g. FSC No. F6/DFS Restt within	As above	MR		
	Road width	T-3 Bldg.	As above	MR		
	Gate widthWidth of internal road	1-5 Blug.	As above	MR		
2.	Number, width, Type & Arrangemen	nts of exits				
2.	a. Number of staircases	Provided & Maintained by 1-3 Bldg. Wight		g. Mgmt.		
į.	Upper floors	Restt. within T-3	As above	MR		
	Basements	NA	NA	NA		
	b. Width of staircases	Provided & Maintained by T-3 Bldg. Mgmt.				
	Upper floors	Restt. within T-3		MR		
	Basement	NA	NA TABLE	MR		
	c. Protection of exits		Maintained by T-3 Blo	MR		
	Fire check door	Restt. within T-		MR		
ı.	 Pressurization 	Restt. within T-				
H	d. No of continuous staircase to terrace	Restt. within T-		MR		
	e. Width of Corridor	Restt. within T-		MR MR		
	f. Door Size	Restt. within T-	CO J NOVINCE THE COSC SALE APPRICA	SOUTH FOR THE SERVICE SERVICE OF THE SERVICE S		
3		Provided & Maintained by T-3 Bldg. Mg Restt. within T-3		MR		
	Fire check door	Restt. within T		MR		
	Sealing of electrical shafts Fig. Pating of shaft door	Restt. within T		MR		
	 Fire Rating of shaft door Water Curtain 	Restt. within T		MR		
	Fire Dampers	Restt. within T	CONTRACTOR I	MR		
-	Smoke managements System	Provided &	Maintained by T-3 B			
	Basements	NA	As above	NA		
	Upper floors	Restt. within 7	C-3 As above	MR		
-	5. Fire Extinguishers			1		
_	Total numbers	J.	15nos	MR		
	• Types	ISI marked	ABC, W.CO2 & 0	CO ₂ MF		
	ISI marking		Required	MI		
	A: 1 Hoge Reels	Provided a	Provided & Maintained by T-3 Bldg. M			
	6. First – Aid Hose Reess Total numbers on each flo					
	• Total numbers on the	D 44 1411	201 7.11	171		
	 Length of hose reel hose 	Restt. within	T-3 30m	M		

8

	Type of detector	Restt. within T-3	Maintained by T-3 Bldg Smoke & Heat	MR	
	Location of Main Panel	Hotel within T-3		MR	
		Hotel within T-3	Upper Basement Provided		
	Location of Repeater Panel	Hotel within T-3	0.0000000000000000000000000000000000000	MR	
	Alternate source of power		Provided	MR	
8.	Hooters' Location	Hotel within T-3	All Areas	MR	
9.	MOEFA Public Address Starter	Restt. within T-3	Provided	MR	
10.	Public Address System Automatic Sprinkler System	Restt. within T-3 Provided MR Provided & Maintained by T-3 Bldg. Mgmt			
	Basements				
		NA Darie idi Ta	As above	NA	
	Upper floors Sprinkles along 6.1	Restt. within T-3	As above	MR	
11.	Sprinkler above false ceiling Internal Hydrants	Restt. within T-3	As above	MR	
	Size of riser/down- comer		ntained by T-3 Bldg		
	and the second s	Hotel within T-3	150 mm	MR	
	Number of hydrants per floor Hose Box	Hotel within T-3	2nos near Restt.	MR	
12.	Yard Hydrants	Hotel within T-3	2nos near Restt.	MR	
12.	(Fig. 10.776, 20.797)	Provided & Main	ntained by T-3 Bldg	. Mgmt.	
	Total number of hydrants	Hotel within T-3	As above	MR	
12	Hose Box	Hotel within T-3	As above	MR	
13.	Pumping Arrangements Provided & Maintained by T-3 Bldg. Mgm				
	Ground Level				
	Discharge of main pump	Restt. within T-3	As above	MR	
	Head of main pump	Restt. within T-3	As above	MR	
	Number of main pumps	Restt. within T-3	As above	MR	
	> Jockey pump out put	Restt. within T-3	As above	MR	
	> Jockey pump head	Restt. within T-3	As above	MR	
	Standby Pump out put Standby Pump Head	Restt. within T-3	As above	MR	
	o mileo y r unip ricad	Restt. within T-3	As above	MR	
	Auto Staring/Manual stopping	Restt. within T-3	As above	MR	
	> Pump House Access	Restt. within T-3	As above	MR	
	Terrace level				
	Discharge of pump	NA	NA	NA	
	➤ Head of the pump	NA	NA	NA	
	> Power supply	NA	NA	NA	
	> Auto starting of pump	NA	NA	NA	
14.	Captive water Storage for fire fighting Provided & Maintained by T-3 Bldg. Mgm				
	 Underground tank capacity 	Restt. within T-3	As above	MR	
	Draw of connection	Restt. within T-3	As above	MR	
	Fire service inlet	Restt. within T-3	As above	MR	
	➤ Access to tank	Restt. within T-3	As above	MR	
	Overhead Tank capacity	Restt. within T-3	As above	NA	
15.	Exit Signage	Restt. within T-3	As above	750-2276	
16.	Provision of Lifts	Provided & Mai	ntained by T-3 Bldg	MR	
	> Pressurization of Lift Shaft	Restt. Within 1-3	As above	MR	
	Pressurization of lift lobby	Restt. within T-3	As above	MR	
	Communication in lift Car	Restt. within T-3	As above	MR	
	Fireman's Grounding Switch	Restt. within T-3	As above	MR	
	➤ Lift Signage	Restt. within T-3	As above	Photograph 2 Programme 2 Progr	
17.	Standby power supply	Restt. within T-3	As above	MR	
18,	Refuge Area		113 40070	MR	
	> Total area	Restt. within T-3	As above	MR	
	▶ Location	Restt. within T-3	As above	MR	

86

9.	Fire control room	Provided & Maintained by T-3 Bldg. Mgn		
	Detector system panel	Restt. within T-3	As above	IVIN
	Flow Switch Panel	Restt. within T-3	As above	MR
		Restt. within T-3	As above	MR
	> PA System Panel	Restt. within T-3	As above	MR
	➤ Battery backup		As above	MR
	Building Floor Plans	Restt. within T-3	X .	MR
20.	Special Fire Protection Systems for Protection of special Risks, if any;	Restt. within T-3	As above	1

The fire protection system provided in the building/premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/SZ/2021/204 dated 31/08/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Manoj Kumar Sharma

Designation: DO (SD)

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

Dineta 8 51 2014

utter is puros for your sing. pl

uplaceded