



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

F.6/DFS/MS/School/SZ/2024/ 475 No.

Dated: 29 /05/2024

## FIRE SAFETY CERTIFICATE

Certified that the Rajkiya Sarvodaya Kanya Vidyalaya, Moti Bagh-1, New Delhi-110021 (ID-1719073), building comprised of Ground & 2 upper floors, was issued fire safety certificate by this department vide letter No. F.6/DFS/MS/School/2018/SZ/117 dated 11/02/2021. The said school was re-inspected by the officer concerned of this department on 17/05/2024 in the presence of Sh. Baljit Singh (Estate Manager) of the school and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in according with Director of Education Circular No. F.16/Estate/CC/Fire/Safety/2011/3298-3398 dated 01/03/2011 and that the building/premises is fit for occupancy class "Educational" (Group-B) with effect from the date of issuance of this certificate for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 29 05 2024 at New Delhi by

DELHI FIRE SERVICE

## Copy to: -

- 1. The Principal, Rajkiya Sarvodaya Kanya Vidyalaya, Moti Bagh-1, New Delhi-110021.
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape / entry / exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times. Any loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The foam is available on www.dfs.delhigovt.nic.in.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

1.	Name & address of the building	ON REPORT Rajkiya Sarvoda	aya Kanya Vidyal	aya, Moti	
2.	Type of O				
- 3.	Type of Occupancy	Bagh-1, New Delhi-110021 (ID-1719073) Educational (Group-B)			
4.	Building Comprised of	Ground & 2 upper floors.			
	Type of Case	Renewal			
5.	Details of previous NOC No.	F.6/DFS/MS/School/SZ/2021/117 dt.11/02/202			
6.	Fire Safety directives Letter No.	F.16/Estate/CC/Fire/Safety/2011/3298-3398			
		dated 01/03/2011			
7.	Date of inspection	17/05/2024			
8.	Name of the Inspecting Officer	Santosh Kumar (ADO/SJ)			
9.	Name and designation of Officer	Sh. Baljit Singh (Estate Manager)			
	from the building side	Sii. Daijit Singii (Estate Manager)			
10.	Year of Construction	1968			
11.	Applicant's letter No	Email Id skymotibagh1@gmail.com dated			
		10/05/2024			
S. No.	Minimum standards on fire	Requirements/	Provided at	Remarks	
	prevention and fire safety U/R 33	DOE Circular	site	MR/NMI	
	A 1	Dated 01/03/2011	Site	MINIMA	
1.	Access of building	du		17	
	Road width	Required	9m	MR	
	Gate width	NA	NA	NA	
AK	<ul> <li>Width of internal road</li> </ul>	NA	NA	NA	
2.	Number, width, Type & Arrangements	s of exits			
	a. Number of staircases	* Mail 1110 20		_	
	Upper floors	Required	2 Nos	MR	
	Basements	NA	NA	NA	
	b. Width of staircases	4.	//		
j.	Upper floors	1.50 / 0.75m	2.10m & 1.90m	MR	
	Basements	NA	NA	NA	
	c. Protection of exits				
17/0	Fire check door	NA	NA	NA	
100	Pressurization	NA	NA	NA	
111	d. No of continuous staircase to terrace	Required	1	MR	
4 1 to	e. Width of Corridor	N/A	1.5m	NA	
1.	f. Door Size	1.0m	1.0m	MR	
3.	Compartmentation	1/4	1000		
1.5	Fire check door	NA	NA	NA	
	Sealing of electrical shafts  Fire Peting of the Advances	NA	NA	NA	
10 m	Fire Rating of shaft door     Water Curtain	NA	NA	NA	
17.67	Fire Dampers	NA NA	NA	NA	
4.	Smoke managements System	NA	NA	NA NA	
	• Basements	NA	NA	17.4	
1 1	Upper floors	NA	NA NA	NA NA	
5.	Fire Extinguishers		INA	NA	
	Total numbers	14 Nos	15 Nos		
	• Types	ABC/W.CO <sub>2</sub>	- Company of the Comp	MR	
,	ISI marking	ISI Marked	ABC & CO <sub>2</sub>	MR	
6.	First-Aid Hose Reels	ankou	Provided	MR	
1	Total numbers on each floor	02 Nos			
	Length of hose reel hose	30m	Provided	MR	
3	Nozzle diameter	5mm	Provided	MR	
		SHIII	Provided	MR	

7.	Automatic fire detection and alarming sy	stem		
,	Type of detector	NA	NA	NA
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
8.	MOEFA	NA	NA	NA
9.	Public Address System	NA	NA	NA
ESSAU.	Automatic Sprinkler System			
10.	Basements	NA	NA	NA
	Upper Floor	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants			
11.	Size of riser/down- comer	NA	100mm	NA
	Number of hydrants per floor	NA	02 Nos	NA
	Hose Box	NA	02 Nos	NA
12.	Yard Hydrants			
12.	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13.	Pumping Arrangements		- Change	
	Ground Level		's read of	
	➤ Discharge of main pump	NA	NA	NA
	> Head of main pump	NA	NA -	NA
	> Number of main pumps	NA	NA	NA
	> Jockey pump out put	NA	NA	NA
	> Jockey pump head	NA	NA	NA
	➤ Standby Pump out put	NA	NA	NA
	> Standby Pump Head	NA	NA	NA
	➤ Auto Staring/Manual stopping	NA	NA	NA
	➤ Pump House Access	NA	NA	NA
	Terrace level	+ 1		
	➤ Discharge of pump	450 LPM	Provided	MR
	> Head of the pump	40m	Provided	MR
	> Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting		210 11000	
- 11	Underground tank capacity	NA	NA	NA
	> Draw of connection	NA	NA	NA
	> Fire service inlet	NA	NA	· NA
	> Access to tank	NA NA	NA	NA
	Overhead Tank capacity	10,000 ltr	10,000 ltr	MR
		20,000 111	10,000 10	4530.740,000
15	Exit Signage	Required	Provided	MR
15 16.		Required	Provided	MK
3000	Exit Signage Provision of Lifts	•		NA NA
3000	Exit Signage  Provision of Lifts  Pressurization of Lift Shaft	NA	NA	
3000	Exit Signage Provision of Lifts	NA NA	NA NA	NA NA
3000	Exit Signage  Provision of Lifts  Pressurization of Lift Shaft  Pressurization of lift lobby  Communication in lift Car	NA NA NA	NA NA NA	NA NA NA
3000	Exit Signage  Provision of Lifts  Pressurization of Lift Shaft  Pressurization of lift lobby  Communication in lift Car	NA NA NA	NA NA NA	NA NA NA
3000	Exit Signage  Provision of Lifts  Pressurization of Lift Shaft  Pressurization of lift lobby  Communication in lift Car  Fireman's Grounding Switch  Lift Signage	NA NA NA NA NA	NA NA NA NA NA	NA NA NA NA
16.	Exit Signage Provision of Lifts  Pressurization of Lift Shaft Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch Lift Signage Standby power supply	NA NA NA	NA NA NA	NA NA NA
16.	Exit Signage  Provision of Lifts  Pressurization of Lift Shaft  Pressurization of lift lobby  Communication in lift Car  Fireman's Grounding Switch  Lift Signage	NA NA NA NA NA	NA NA NA NA NA	NA NA NA NA

19.	Fire control room			
	<ul> <li>Detector system panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Battery backup</li> <li>Building Floor Plans</li> </ul> Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
20.		NA	NA	NA
		NA	NA	NA

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection. The shortcomings issued by this department vide letter No. F.6/DFS/MS/School/2024/SZ/77 dated 22/02/2024 found rectified.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/School/SZ/2021/117 dated 11/02/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

DO (SD)

mul

p 20/2

1 21 5 20m

Any S

dir,

it juder is sump for your sing.

Director My g m/s/29

Home