

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No.F.6 DFS/MS/School/2024/SZ/508

Dated: 06/06/2024

FIRE SAFETY CERTIFICATE

Certified that the Govt. Boys Senor Secondary School (ID-1720034) located at Ghitorni, New Delhi 110030 comprised of 01 Block, Ground plus three upper floor owned/occupied by Directorate of Education, Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2021/SZ/894 dated 29/10/2021. The said premises was re-inspected by officer concerned of this department on 27/05/2024 in presence of Mr. Krishan Kumar (Principal) and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational Building Group - B" with effect from 06 / 06 / 2024 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delbi Fire Service Rules 2010.

Issued on 06/06. 2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Principal, Govt. Boys Senor Secondary School at Ghitorni, New Delhi 110030 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-54.

Conditions for the validity of Fire Safety Certificate:-

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

This certificate cannot be treated as regularization of unauthorized construction, if any.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior





-	Nome & Add State Color Time Property Color Tim					
1	Name & Address of the Building	Govt. Boys Senor Secondary School Ghitorni, New Delhi 110038 (ID-1720034)				
2	Type of Occupancy	Educational Building				
3	Building Comprised of	One Block, Ground plus Three upper floor (old Block G+1 Not for use.)				
4	Type of Case	Renewal				
5	Details of Previous NOC					
6	Fire Safety Directives Letter No	F6/DFS/MS/School/2021/SZ/894 dated 29/10/2021 NBC Part IV / UBBL 2016				
7	Date of Inspection	27/05/2024				
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
9	Name & Designation of Officers from the building side	Mr. Krishan Kumar (Principal)				
10	Year of construction	2021				
-11	Applicant letter No.					
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC Part IV / UBBL 2016	Provided at Site	Remarks MR/NMR		
1	Access to Building.	3				
HIE	Road width	Required	6 mtr	MR		
	Gate width	Required	6 mtr	MR		
	Width of internal road	-NA-	-NA-	-NA-		
2	Number, width, type & arrangement of exits.			0 ZI		
	a) Number of Staircase					
	Upper floors.	02 No	04 No's	MR		
	➤ Basement floor.	-NA-	-NA-	-NA-		
	b) Width of Staircase					
	> Upper floors	1.50 mtr	1.50 mtr each	MR		
	> Basement floor	-NA-	-NA-	-NA-		
	c) Protection of exits		anto magnification of the			
	➤ Fire check door	-NA-	-NA-	-NA-		
	> Pressurization	-NA-	-NA	-NA-		
	d) No. of continuous staircase to terrace	-NA-	-NA-	-NA-		
	e) Width of corridor	-NA-	lava NA Task	-NA-		
	f) Door size MAL DOLA 2.	1.2 mtr	Provided with double door	MR		
3	Compartmentation.	Yengla - was a garast black on				
977	Fire check door.	-NA-	-NA-juny gytte	-NA-		
	Sealing of electrical shafts.	-NA-	_ Jacoba -NA-	-NA-		
3.8	Fire rating of shaft door.	-NA-	NA	-NA-		
	Water curtain	-NA-	-NA-	-NA-		
dell	Fire dampers.	-NA-	-NA-	-NA-		
4.	\$moke Management system.		a thai ilgal tudi cruca			
29.1-1	Basement	30a/c per hour	-NA-	-NA-		
11/12	Upper floors	12a/c per hour	-NA-	-NA-		
5.	Fire Extinguishers.		The section of V			
- 5.7	Total numbers	Required	20 Nos	MR		
	● Types	CO ² &ABC	CO ² & ABC	MR		
200	ISI Marking	ISI mark	Provided	MR		
6.	First Aid Hose Reels.					
	Total numbers on each floor. Length of hose-reel hose.	-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		



	γ2	110	आज़ा अम्	तु महोत्स
-	Nozzle Diameter	-NA-	-NA-	-NA-
7	Automatic fire detection & alarming system.			
-	Type of detectors	-NA-	-NA-	-NA-
	Location of Main Panel Location of Repeater Panel	-NA-	NA -NA	-NA-
u-11	Alternate source of power	-NA-	-NA-	-NA-
- 1	Hooter's location	-NA-	-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8.	MOEFA	-NA-	-NA-	-NA-
9.	Public Address System	-NA-	-NA-	-NA-
10.	Automatic Sprinkler System			
10.	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.		nashadosta na da	A PAPER
sem5	Size of Riser/Down-comer	Required	100 mm	MR
	Number of Hydrant per floor	Required	02	MR
	Hose box.	Required	02	MR
12.	Yard Hydrants.		(i) (ii) *	
A	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.		Sanday of Subsect	
20.	Ground Level		maylr sagul -	
	Discharge of main pump.	-NA-	-NA-	-NA-
	➤ Head of main pump.	-NA-	August-NA- unin //	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	 Standby Pump head. Auto Starting / Manual Stopping. 	-NA-	-NA-	-NA-
	> Auto Starting / Manual Stopping. > Pump house access.	-NA-	-NA-	-NA-
	The Common Commo	-NA-	PAGGE (D3 III KHE I)	147
	Terrace Level	2 x 450 LPM	Provided	MR
	Discharge of pump.	40 LFW	Provided	MR
	➢ Head of pump.➢ Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
		Required	11011000	
14.	Captive water storage for fire fighting.	-NA-	-NA-	-NA-
	 Underground tank capacity. Draw-off connection. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
_ A	> Fire Service Inlet. > Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	10,000 ltr	Provided	MR
15		Required	Provided	MR
15.				-NA-
16.	Prevision of Lifes. Pressurization of fift shaft.	-NA-	-NA-	-NA-
- ,	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in tift car.	-NA-	-NA-	-NA-
1	• Fireman's switch.	-NA-	-NA-	-NA-
1	Lift signage.	-NA-	Provided	MR
17	The state of the s	Required	riovided	
18		2 1	-NA-	-NA-
1	Total area	-NA-	3.00.5	

2



19.	Location Fire Control Room.	-NA-	-NA-	-NA-
	Detector system panel)72 T		3330.399
- 1	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup Building floor plan	-NA-	-NA-	-NA-
20.		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/School/2021/SZ/894 dated 29/10/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design. ADO (BCP)

DO (SI