

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2024/ 220

Dated: 12/07 /2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Moti Mahal Restaurant located at 3704, Netaji Subhash Marg, Darya Ganj, Delhi -02, comprised of ground floor only was granted FSC by this department vide letter no. F6/DFS/MS/EH/NDZ/2021/111 dated 27.04.2021. The building/ premises was reinspected by the officer concerned of this department on 05.07.2024 in presence of Mr. Vinod Chadha (Owner) and found that the premises/building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy class Group-D "Assembly Building" Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 12 07 2024 at New Delhi by

i Fire Service

el: 011-23414000

## Copy to:-

- 1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi: - Ref. MHA Portal ID. No. 2024062509898 dated 25.06.2024.
- 2. The Medical Officer of Health, Health Department, MCD, Civic Centre, Minto Road, New Delhi- 02.
- 3. The Licensee, M/s Moti Mahal Restaurant at 3704, Netaji Subhash Marg, Darya Gani, Delhi.

## Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 8. Any changes in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

	INSPECTION Name & address of the building	M/s Moti Mahal Restaurant at 3704, Netaji Subhash Marg, Daryaganj, Delhi- 02.			
	Building is comprised of	Ground floor only			
-	Type of Occupancy	Assembly (Restaurant)			
S. Type of Geogramsy				dated	
	Type of Case	F6/DFS/MS/EH/NDZ/2021/111 dated			
5. Details of Frevious 1 50		27.04.2021			
6. Fire Safety direction letter No		NA			
7. Date of Inspection		05.07.2024			
OCCorne		Sumit Kumar, ADO (SPM)			
<ol><li>Name of the designation of Officer</li></ol>		Mr. Vinod Chadha (Owner)			
	from the building side	1947			
10	Year of Construction	Online applicat	ion I.D. 202406250	)9898 dated	
11.	Applicant's letter No	Online application I.D. 2024062509898 dated 25.06.2024			
S.No	Minimum Standards on fire prevention	Requirement/ NBC	Provided at Site	Remarks MR/NMR	
	and fire safety U/R 33	NBC			
1	Access to building	106	24 m	MR	
	Road width	06 m	NA	NA	
	Gate width	NA	N/A	N/A	
	The state of the s	N/A	14/21	7	
2	Number, Width, Type and Arrangement	of Exits.			
-	A. Number of Staircases		NA	NA	
	upper floor	NA	NA	NA	
	Basement	NA	NA	NA	
	B. Width of Staircases	NA NA	NA	NA	
	Ground to mezzanine floor		NA	NA	
	Basement	NA	INA		
	C. Protection of exits		NA	NA	
	Fire check door	NA	3 20 3	NA	
	Descurization	NA	NA	NA NA	
	D. No. of continuous staircases to terrace	NA	NA	NA	
	E. Width of Corridor	NA	NA		
	F. Door Size (Exits)	1.5 m	1.69 m, 0.90 m	MR	
3	Compartmentation	NA	NA	NA	
	Fire check door	NA NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	Fire rating of shaft door		NA	NA	
	Water curtain	NA		NA	
	Fire Dampers	NA	NA	INA	
4	Smoke Management System.		INA	NA	
ŀ	Basement	NA	NA	MR	
	Ground floor	12 a/c per	Natural	MIR 84	

	Fire Extinguisher		Lan	MR	
	Total numbers	04 no.	08 no.	MR	
	types	ABC & CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR	
	IS marking	Required	Provided	WAR	
5	First-aid-Hose Reels.			MR	
	Total numbers of ground floor	01 no.	01 no.	MR	
	Length of hose reel hose	30 m	30 m	LARCHTEC	
- 1	Nozzle diameter	05 mm	05 mm	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors (Smoke/heat)	Required	Provided	MR	
	Location of main panel	Required	Provided		
	Location of repeater panel	NA	NA	MR	
	Alternate source of power	Required	Provided		
	Hooters	Required	Provided	MR	
8	MOEFA	Required	Provided	MR	
9	Public address System.	NA	NA	NA	
10	Automatic Sprinkler System.		Tava	NA.	
10	Kitchen	NA	NA	NA NA	
	Upper floor	NA	NA	-0365	
	sprinkler above false ceiling	NA	NA	NA	
11	Internal Hydrants				
**	size of riser/down-comer	100 mm	100 mm	MR	
	Number of hydrants each floor	1 no.	1 no.		
	Hose box each floor	1 no.	1 no.	MR	
12	Vard Hydrants.				
	Total number of hydrants	NA	NA	200200	
	Hose Box	N.A.	NA	NA	
13	Pumping Arrangements.				
	Ground Level	450 LPM	450 LPM	MR	
100	Discharge of main Pump	450 LPM 40 m	430 LFW	MR	
ĺ	> Head of Main Pump		01 no.	MR	
-31	> Number of main pumps	01 no.	NA	NA	
	> Jockey pump out put	NA -			
	<ul><li>Jockey pump head</li><li>Standby pump out put</li></ul>	NA NA	NA NA	NA NA	
		escone.	Section 25		
		NA	NA	NA	
		NA	NA	NA	
		NA	NA NA	NA	
100		NA NA	NA NA	NA NA	
	<ul><li>Discharge of pump</li><li>Head of the Pump</li></ul>		50.554.000		
114	20 20	NA NA	NA NA	NA	
	<ul><li>Power supply</li><li>Auto Starting of pump</li></ul>			NA	
75	/ Auto Starting of Pamp	NA	NA	NA	

	Captive Water Storage for Fire Fightin	13,000 Liters	13,000 ltrs.	MR	
	Underground tank capacity		NA NA	NA	
- 1	Draw-off connection	NA		NA	
- 1	Fire service inlet	NA	NA	Parties.	
	Access to tank	NA	NA	NA	
- 1	Overhead Tank capacity	NA	NA	NA	
		Required	Provided /	MR	
5	Exit Signage.				
6	Provision of Lifts.	NA	NA	NA	
	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of Lift lobby Communication in lift car	NA	NA	NA	
	Firemen's grounding switch	NA	NA	NA	
	Lift Signage	NA	NA /	NA	
17	Standby power supply	Required	Provided /	MR	
18	Refuge Area.				
10	Total area	NA	NA	NA	
	Location	NA	NA	NA	
19	Fire Control Room				
17	Detector system panel	NA	NA	NA	
	Flow switch panel	NA	NA	NA	
	PA system panel	NA	NA	NA	
	Batter backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20	Special Fire Protection systems for protection of special Risks, if any:	LPG bank near the kitchen: Protected by sprinkler		MR	

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/EH/NDZ/2024/152 dated 23/04/2024 have been rectified.

In view of the deemed compliance of minimum standards of fire prevention and fire safety letter required under the Rules, the **FSC** issued vide measures F6/DFS/MS/EH/NDZ/2021/111 dated 27.04.2021 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

> Signature of the Inspecting Officer Name **Sumit Kumar**

> > Designation

ADO (SPM)

Dinecter