Dated: 12 /07/2024

Ok Delhi Fire

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

No. F6/DFS/MS/2024/Cny | SWZ | 299 NEW DELHI FIRE SAFETY CERTIFICATE

Certified that the building of M/s Hotel Maurya Heritage, Located at Ground, 1st, 2nd, & 3rd floor 7A/58, WEA Channa market, Karol Bagh, New Delhi-110005, in a building comprised of basement, ground plus four upper floors using, ground floor (reception & 02 guest rooms), first floor (03 guest rooms), second & third floor (05 guest rooms each floor) (Total=15 guest rooms) & pantry with store room on 4th floor / terrace (now sealed/closed) was issued FSC vide Letter No F6/DFS/MS/GH/SZ/2021/371, dated 08/09/21. The premises was re inspected by the officer concerned of this department on 16/07/2024 in the presence of Sh. Prem Pandey and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" (guest house) at ground floor (reception & 02 guest rooms), first floor (03 guest rooms), second & third floor (05 guest rooms each floor) (Total=15 guest rooms) with effect from 22 07 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on . 22 07/2024. at New Delhi by.

Copy to:

1. The Joint. Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi.

2. The Manager, M/s Hotel Maurya Heritage, Located at Ground, 1st, 2nd, & 3rd floor 7A/58, WEA Channa market, Karol Bagh, New Delhi-110005.

## Following fire safety directives must be adhered to:-

1. 4th floor shall not be used for any purpose as undertaking given by owner.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction,

7. Basement strictly shall be kept vacant as seen during inspection.

The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

## INSPECTION REPORT

 Name & address of the building: M/s Hotel Maurya Heritage, Located at Ground, 1<sup>st</sup>, 2<sup>nd</sup>, & 3<sup>rd</sup> floor 7A/58, WEA Channa market, Karol Bagh, New Delhi-110005.

2. Type of Occupancy

:Lodging or rooming "A-1"

3. Type of Case: Renewal (Running at Ground, 1<sup>st</sup>, 2<sup>nd</sup>, & 3<sup>rd</sup> floor in a building comprised of Ground +4 Upper Floor & pantry with staff room on 4<sup>th</sup> floor/ terrace)( Now sealed)

4. Details of previous NOC: F6/DFS/MS/GH/SZ/2021/371, dated 08/09/21

5. Fire Safety directives Letter No.: Nil

6. Date of inspection

: 16/07/2024

7. Name of the Inspecting Officer: ADO (DWK)

8. Name and designation of Officer

from the building side

: . Sh.Prem Pandey

9. Year of Construction

: 2000- 2001

10. Applicant's letter No.

: 2024062309837, dated 25/06/2024

S No	Minimum standards on fire prevention and fire safety U/R 33		As per N/30, N/31 & N/32		Prov site	Provided at site		Remarks MR/NMR	
1.	Access of building				·   D :1			MR	
-	Road width	6 mtr			Provid	Provided			
	Gate width		1.50 C 100 C 1			accessible from road			
	Width of internal road	NA	55 W. C.					NA	
2.	Number, width, Type & Arrang	geme	ents of e	xits					
	a. Number of staircases					100		ld seed	
	Upper floors     Basements		01		01	MR (Being old cas		id case)	
			NA.		NA	NA	Ar II		
	b. Width of staircases							11 \	
	Upper floors	1,200.		23m		MR (Being old case			
	Basements			NA	NA		NA		
1	c. Protection of exits								
	Fire check door	N	NA NA			A NA		NA	
1	Pressurization	N				NA		NA	
	d. No of continuous	_AMPLICA			104	01		MR	
	staircase to terrace	10				6			
	e. Width Of Corridor		1.25m		Provide	Provided			
	f. Door Size		ld case		0.80 m	·MR	(Being	old case)	
3.	Compartmentation	+	./						
<u> </u>	Fire check door	N	NA NA			NA			
	Sealing of electrical		Required			Sealed		MR	
	shafts					79			
	Fire Rating of shaft		. NA·			NA		NA	
	door				17				
	Water Curtain	1	NA			NA		NA	
	Fire Dampers	1	NA			NA		NA	

X0 6

## N-35

4.	Smoke managements System	n NIA	NA NA			NA ·		
	Basements	12 a	NA 12 a/c per hour			Provided		
	Upper floors	12 a	e per no	ui I	T			
5.	Fire Extinguishers	103	Nos.		Pr	Provided		MR
	<ul> <li>Total numbers</li> </ul>	1000	08. C & CO2			O <sub>2</sub> & ABC		MR
	• Types		uired		11-100	rovided		MR
	IS marking      Ail Hard Books			TIOTAGE		OTAGE		
6.	First – Aid Hose Reels  Total numbers on ea	ch	02		Pr	Provided		MR
	floor	.011	4					) (D
	Length of hose reel 1	hose	30 mtr			rovided		MR MR
	<ul> <li>Nozzle diameter</li> </ul>		5 MM		Pı	Provided		IVIK
7.	Automatic fire detection and	d alarmin	g system	ì ·	l n			MR
	<ul> <li>Type of detectors</li> </ul>	39055	CO detectors			Provided		MR
	Location of Main Panel	Req	Required			Provided		
	<ul> <li>Location of Repeate Panel</li> </ul>	r NA	NA N		JA .			NA
	Alternate source of power	Req	Required Provi		led		MR	
	Hooters' Location	NA			N/	NA		NA
8.	MOEFA	Rea	uired	Provid	ded			MR
9.	Public Address System			Provi	100 m	FILE		MR
10.	Automatic Sprinkler System							2770.00
	Basements	NA	NA			NA		NA
	Upper Floor	NA				NA		NA
	<ul> <li>Sprinkler above fals ceiling</li> </ul>	e NA	NA			NA		NA
1.	Internal Hydrants:					1	•	LATA
	Size of riser/down-		and the same of th			NA		NA
	<ul> <li>Number of hydrants</li> </ul>	per floor	r NA			NA		NA
	<ul> <li>Hose Box</li> </ul>		NA			NA		NA
2.	Yard Hydrants		Đ	7.5				
	Total number of hyd	lrants	NA			NA		NA
	Hose Box	- 5	NA		R	NA		NA
3.	Pumping Arrangements:							
	Ground Level							
	<ul> <li>Discharge of main p</li> </ul>	ump [	NA			NA		NA
	> Head of main pump		NA			NA		NA
	Number of main pumps		NA			NA		NA
	Jockey pump out pu	t	NA			NA		NA
	Jockey pump head		NA			. NA		NA
	Standby Pump out p		NA		NA .		*_	NA
	Standby Pump Head		NA .		NA			NA
	Auto Staring/Manua stopping		NA			NA		NA
	<ul><li>Pump House Access</li><li>Terrace level</li></ul>		NA			NA		NA
	<ul><li>Discharge of pump</li></ul>	-	450 lpm			Provided		MR
	> Head of the pump	}	450 lpm 30 mtrs		Provided			MR
	> Power supply	ŀ			<u> </u>			MR
	> Auto starting of pur	g	Required		Provided			MR
- 1	, rico starting or pun	r	Require	a	20	Provided		IVIK



4.	Captive water Storage for fire fi	NA	9	NA	N.
T	Under ground tank			1.11.	NA
	oonacity	NA		NA	NA
	> Draw off connection	NA NA		NA	NA NA
	➤ Fire service inlet	NA		NA	NA MR
	> Access to tank			3000 ltr	
- 1	<ul> <li>Overhead Tank</li> </ul>	Old	case	3000 14	
	capacity		wired	Provided	MR
15	Exit Signage	Required		1	
16.	Provision of Lifts	NA	NA	NA	
	> Pressurization of Lift Sh	nan	NA NA	NA	NA
	> Pressurization of lift lob	Required	Provided	MR	
	> Communication in lift (	Required	Provided	MR	
	> Fireman's Grounding				Required
	Switch  > Lift Signage		Required	Provided	MR
17			Required	Provided	MR
17.		-	Require		1
18.	Refuge Area  > Total area		NA	NA	NA
> Location			NA	NA	NA
19.					T and the
17.	> Detector system panel	NA NA NA		NA	NA
	Flow Switch Panel			NA	NA
	> PA System Panel			NA	NA
	> Battery backup		uired	Provided	. MR
1	> Building Floor Plans	NA		NA	NA
20		s for any;	NA	NA	NA

The fire protection systems provided in the building were test checked and found

functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/SZ/2021/371, dated 08/09/21 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended. If approved the FSC may be issued.

Signature of the Inspecting Officer

Name Sh. Udaivir Singh Designation: ADO (DWK)

CENC2) 11 11

19 H 1200

Dinestary (6)

Im

23/2/2 D