

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2024/ 308

Dated: 30/07/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Al - Sana Guest House situated at 8-12 to 15 SF & TF, Bazar Matia Mahal, Jama Masjid, Delhi-06, comprised of Ground + 03 upper floors: Ground floor - (commercial use), 1st floor - (reception), 2nd floor - (07 guest rooms + 01 store room) & 3<sup>rd</sup> floor - (07 guest rooms + 01 staff room), total 14 guest rooms was granted FSC by this dated 25.08.2021. F6/DFS/MS/GH/NDZ/2021/334 department vide letter no. building/premises was re-inspected by officer concerned of this department on 19.07.2024 in presence of Mohd. Javed (Manager) and found that building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 19.07.2024 stating not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)", 2<sup>nd</sup> floor - (07 guest rooms) & 3<sup>rd</sup> floor - (07 guest rooms) for total 14 guest rooms upto 3rd floor only, with effect from .. 30 07 2024...... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and 

Delhi Fire Service

Tel: 011-23414000

Copy to:-

1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.

2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defense Colony, New Delhi w.r.to ID No. 2024070910711 dated 09.07.2024.

3. The Licensee, M/s Al - Sana Guest House at 8-12 to 15 SF & TF, Bazar Matia Mahal, Jama Masjid, Delhi-06.

## Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

## -N 27-INSPECTION REPORT

1.	build	te and address of the Maing:	M/s Al - Sana Guest House situated 8-12 to 15 SF, TF Bazar Matiya Mahal, Jama Masjid, Delhi-06.			
	Тур	f occupancy with Residential (Group A-1)				
	details of floors:		(Ground + 03 upper floors)			
		Gr	ound floor- (commerci	al use)		
		1 <sup>st</sup>	floor - (reception) floor- (07 guest rooms			
		2 <sup>nd</sup>	floor- (07 guest rooms	+ 01 store room),		
_	<b>-</b>	3 <sup>rd</sup>	floor- (07 guest rooms	+ 01 starr room)		
3.		e of case: Re	newal case /DFS/MS/GH/NDZ/202	1/234 dated 25.08.	2021	
4.		ails of previous FSC: F6		1/334 dated 2510		
5.		safety directives no.: NA				
6.		e of inspection: 19.	.07.2024 mit Kumar, ADO (SPM	)		
7.	offi		mit Kullai, ADO (52	4		
8.	_	ne and designation of the		TETO		
0.		cer from the building M	ohd. Javed (Manager)			
	side			2		
9.		or of construction: 194	47	24070010711 dated	09.07.2024	
10.		erence letter no.: On	47 line application I.D. 202	240/0910/11 dated		
			V.			
	·	CE	Requirements	Provide at site	Remarks MR/NMF	
S,	Mini	mum standard of Fire ention and Fire Safety U/R 33	(Existing Fire &	(PSS)	MIKINIMI	
No	Prev	ention and Fire Salety Office	Safety Measures)			
	A	ess to Building			NA	
1		Road width	NA	12 m (approx)	NA NA	
	A B	Gate width	NA	NA	NA	
	C	Width of internal roads	NA	NA	INA	
_	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ber, Width, Type & Arrangeme	ent of Exits			
2		No. of Staircase:		_	T	
1	A	PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PROPER	01 no.	01 no.	MR	
		a) Upper Floor b) Basements	NA	NA	NA	
1		Width of the Staircase:			1	
	В	a) Upper floors	1.0 m	1.2 m	MR	
		b) Basements	NA	NA	NA	
	C Protection of Exits				1574	
		a) Fire Check Door	NA	NA	NA	
		b) Pressurization	NA	NA	NA	
		,				
1	D	No. Of continuous staircase to	01 no.	01 no.	MR	
1 4	D	terrace:		170		
	F	Width of the corridor	NA	NA	NA	
	E	Door size	1.0 m	1.06 m	MR	
$\vdash$		partmentation:				
3	Con			<b></b> -	Tara	
	A	Fire Check doors	NA	NA	NA	
	-	Cooling of Clastrian Chafe	NA	NA	NA	
	В	Sealing of Electrical Shafts	IWI		_	
	C	Fire rating of shaft Doors	NA	NA	NA	
	-	Water curtain	NA	NA	NA	
	D	water curtain	INA	TAX.	Lux	
	E	Fire dampers	NA	NA	NA	
		,		1		
4	Sm	oke management System:				
4	A	Upper floors	12 ACPH	Natural/Exhaust	MR	
				Fans		
	В	Basements	NA	NA	NA	
5	Fire	extinguishers				
	A	Total numbers	06 no.	06 no.	MR	
	B	Types	CO2, ABC		presenter.	
	11	1537	The Control of the Co	CO2, ABC	MR	
	C	ISI marking	Required	Provided	MR	

+	A	st Aid Hose reel Total no. at each floor	01 No (2 <sup>nd</sup> &	01 No (2 <sup>nd</sup> &	MR			
	A	I otal iio. at each Hoof	3 <sup>rd</sup> floor)	3 <sup>rd</sup> floor)				
+	D	I	30 mtrs	30 mtrs	MR			
H	B	Length of Hose Reel	5 mm	5 mm /	MR			
$\dashv$	C	Nozzle diameter		Jimi				
(1). 		tomatic Fire Detection and Alarm S	Required	Provided (	MR			
	A B	Type of Detectors -(CO) type Location of main Panel	Required	Provided at /	MR			
					NA			
		Location of Repeater Panel	NA	NA	MR			
		Alternate power Source	Required	Provided	MR			
	E	Hooter's location	Required	Provided	NA			
8		DEFA	NA	NA	MR			
9		blic Address System	Required	Provided	MIK			
10	Au	tomatic Sprinkler System	T	Tara	NA			
	Α	Basement	NA	NA	NA			
		Upper Floor	NA	NA	NA			
	С	Sprinklers above false ceiling	NA	NA	IVA			
11	_	ernal hydrants	Lara	NIA	NA			
	A	Size of the riser/down comer	NA	NA NA	NA			
		No. Of hydrants per floor	NA	NA NA	NA			
-	C	Hose box	NA	INA	INA			
12	_	Tables of headersts	l NIA	NA	NA			
	A	Total no. of hydrants	NA NA	NA NA	NA			
	В	Hose box	INA	INA	IVA			
13	_	mping arrangements Ground Level			_			
	A	a) Discharge of main pump	NA	NA	NA			
		b) Head of main pump	NA NA	NA NA	NA			
		c) Number of main pump	NA	NA	NA			
		d) Discharge of jockey pump	NA NA	NA NA	NA			
		Discharge of Jockey pump	MA	11/2	1471			
		e) Head of jockey pump	NA	NA	NA			
		f) Discharge of Standby pump	NA	NA	NA			
		g) Head of Standby pump	NA	NA	NA			
		h) Auto starting/ manual stopping	NA	NA	NA			
	В	Terrace Level						
		a) Discharge of terrace pump	225 LPM	225 LPM	MR			
		b) Head of terrace pump	25 mtrs	25 mtrs	MR			
		c) Alternate power supply	Required	Required /	MR			
		d) Auto starting of pump	Required	Required	MR			
14	The state of the s							
	A	Underground tank capacity	NA	NA	NA			
		Draw off connection	NA .	NA	NA			
	_	Fire Service Inlet	NA ·	NA	NA			
	E	Access to tank	NA	NA	NA			
	D	Overhead tank capacity	25,00 ltrs	25,00 ltrs /	MR			
15		it Signage	Required	Provided /	MR			
16		ovision of lift						
v.	Α	Pressurization of lift shaft	NA		NA			
		Pressurization of lift lobby	NA		NA			
	C	Communication in lift car	NA		NA			
	D	Fireman switch	NA		NA			
	E	Lift signage	NA		NA			
	04	ndby Power Supply	Required	Provided /	MR			

18	Ref	fuge Area	NA	NA	
	A	location	NA	NA NA	NA
	В	Total area	NA	IM	
19	Fire Control Room		NA	NA	NA
	A	Fire Detection System panel	NA NA	NA	NA NA
_	В	Flow switch panel	NA NA	NA	NA NA
	C	P A system panel	NA NA	NA	NA NA
	D	Battery backup	NA NA	NA	NA NA
	-	- '' I' G-on mion			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/GH/NDZ/2024/187 dated

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2021/334 dated 25.08.2021 is recommended to be renewed for 2<sup>nd</sup> & 3<sup>rd</sup> floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Sumit Kumar Name ADO (SPM) Designation

Director (DA