



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 287

Dated: 06/09/2024

FIRE SAFETY CERTIFICATE

Certified that M/s **The Beer Café** (A unit of BTB Marketing Pvt. Ltd) located at GF-02, Ground Floor, Worldmark-II, Asset-8, Hospitality District, Aerocity, IGI Airport, New Delhi, comprised of Three Basements, Ground, Mezzanine + 06 upper floors but the restaurant running at Ground Floor only, was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/EH/2021/SZ/225 dated 10/09/2021. The premise was re-inspected by the officer concerned of this department on 31/08/2024 in the presence of Mr. Gagan Singh (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the said premise is fit for occupancy class "Assembly Group D" (Eating House) upto 31/03/2027 in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

DELHI FIRE SERVICE

Copy to: -

- 1. The Joint Commissioner of Police, Licensing Branch, First Floor, Police Station Defence Colony, New Delhi-110049 (w.r.t. online MHA ID No. 2024082213011 dated 22/08/2024)
- Authorized Signatory M/s The Beer Café (A unit of BTB Marketing Pvt. Ltd), GF-02, Ground Floor, Worldmark-II, Asset-8, Aerocity, IGI Airport, New Delhi-110037

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working conditions
 at all time as seen during inspection. Any loss of life property due to non-functional fire safety
 measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry.

10-09

1	Name & Address of the Building	ON REPORT The Beer Café (A unit of BTB Marketing Pvt Ltd), GF-02, Ground Floor, Worldmark-II, Asset-8, Hospitality District, Aerocity, IGl Airport, New Delhi-110037			
2	Type of Occupancy	Assembly 'Group-D'			
3	Building comprised of	Three Basements, Mezzanine, Ground & Six			
4	Type of Case	Floors but Restaurant is at Ground Floor only. Renewal			
5	Details of Previous NOC	F.6/DFS/MS/EH/2021/SZ/225 dated 10/09/2021			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	31/08/2024			
8	Name of the Inspecting Officers	ADO (SJ)			
9	Name & Designation of Officers from the building side	Mr. Gagan Singh (Manager)			
10	Year of construction	2014			
11	Applicant letter No. / Online N	MHA ID No. 20	24082213011 dated 2	22/08/2024	
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old FSC Requirements	Provided at Site	Remarks MR/NMR	
1			/lixed/SZ/2023/29 Dt.		
	Road width	Restt within	As above	MR	
	Gate width	Worldmark-2	As above	N/A	
	Width of internal road	Aerocity	As above	N/A	
2	Number, width, type & arrangement of			7	
_	a. Number of Staircase	Provided & Maintained by Building Mgmt.			
	Upper floors	-NA-	As above	-NA-	
	Basement floor	-NA-	As above	-NA-	
	b. Width of Staircase		Maintained by Buildi		
	Upper floors	-NA-	As above	-NA-	
	Basement floor	N/A	As above	-NA-	
	c. Protection of exits	Provided & Maintained by Building Mgmt.			
	Fire check door	-NA- As above -NA-			
	Pressurization	-NA-	As above	-NA-	
	The Annual Company Company	Required	As above	MR	
	d. No. of continuous staircase to terrace	•			
	e. Width of corridor	-NA-	-NA-	-NA-	
_	f. Door size	1.5m x 2 2m & 1.5m (final exit) MR Provided & Maintained by Building Mgmt.			
3	Compartmentation.		As above	-NA-	
	Fire check door.	-NA-			
	Sealing of electrical shafts.	-NA-	As above	-NA-	
	Fire rating of shaft door.	-NA-	As above	-NA-	
	Water curtain	-NA-	As above	-NA-	
	Fire dampers.	-NA-	As above	-NA-	
4	Smoke Management system.	Provided & Maintained by Building Mgmt.			
	Basement	-NA-	As above	-NA-	
	Ground floor/Restt. Area	Required	Exhaust fan provided	MR	
5	Fire Extinguishers.				
-	Total numbers	06 Nos	Provided	MR	
		ABC / CO ₂	ABC & CO ₂	MR	
-	Types ISI Morking	ISI marked	Provided	MR	
150	ISI Marking	TORRESCO PLANSACIONASSECUL			
6	First-Aid Hose Reels.	Provided & Maintained by Building Mgm			
	Total numbers on each floor.	One	As above	MR	
	 Length of hose-reel hose. 	30m	As above	The second second	
	Nozzle Diameter	5mm	As above	MR	

7	Automatic fire detection & alarming	A SA A SA	7	
	Type of detectors	-NA-	As above	-N
	Location of Main Panel	-NA-	As above	-N
	 Location of Repeater Panel 	-NA-	As above	-N
	Alternate source of power	-NA-	As above	-N
	Hooter's location	-NA-	As above	-N
8	MOEFA	Required	Provided	M
9	Public Address System	-NA-	As above	-N
10	Automatic Sprinkler System	Provided &	Maintained by Buil	ding Mg
	Basement	-NA-	As above	-N.
	Upper floors / Restt Area	-NA-	As above	-N.
	Sprinkler above false ceiling	-NA-	As above	-N
11	Internal Hydrants.	Provided &	Maintained by Build	ding Mg
	Size of Riser/Down-comer	-NA-	As above	-NA
	Number of Hydrant per floor	-NA-	As above	-NA
	Hose box.	-NA-	As above	-NA
12	Yard Hydrants.	and the second second	Maintained by Build	100
14	Total number of hydrants.	-NA-	As above	-NA
	Hose box.	-NA-	As above	-NA
13	Alexander of the second	-NA-	713 00010	
13	Pumping arrangements. • Ground Level	Provided &	Maintained by Build	ing Mar
		-NA-	2280 LPM	-NA
	Discharge of main pump.Head of main pump.	-NA-	105m	-NA
	Number of main pumps.	-NA-	2 Nos	-NA
	> Jockey Pump output.	-NA-	180 LPM x 2	-NA
	> Jockey Pump head.	-NA-	105m	-NA
	Standby Pump output.	-NA-	2280 LPM	-NA
	> Standby Pump head.	-NA-	105m	-NA
	Auto Starting / Manual Stopping.Pump House Access	-NA-	Provided Provided	-NA
	•		Maintained by Buildi	
	 Terrace Level Discharge of pump. 	450 LPM	As above	MR
	Head of pump.	40m	As above	MR
	> Power supply.	Required	As above	MR
	> Auto starting of pump.	Required	As above	MR
14	Captive water storage for Fire Fighting	g. (Provided & M	laintained by Building	Mgmt.)
	Underground tank capacity.	-NA-	1,00,000 Ltr	-NA-
	Draw-off connection.	-NA-	Provided	-NA-
	> Fire Service Inlet.	-NA-	Provided Provided	-NA-
	Access to tank.	-NA- 10,000 Ltr	20,000 Ltr	MR
16	Overhead tank capacity. Full Signature	Required	Provided	MR
15 16	Exit Signage. Provision of Lifts.	Provided & M	faintained by Buildin	
	Pressurization of lift shaft.	-NA-	As above	-NA-
	Pressurization of lift lobby.	-NA-	As above	-NA-
	Communication in lift car.	-NA-	As above	-NA-
	• Fireman's switch.	-NA-	As above	-NA-
	2 37 h min - 1	-NA-	As above	-NA-
-	Lift signage. Standby Power Supply	Required	Provided	MR
7	Standby Power Supply	Trequire		
8	Refuge Area Total area	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	• Location			2



19	Fire Çontrol Room.	Provided & Maintained by Building Mgmt.		
19	Detector System Panel.	-NA-	As above	-NA-
	 Flow Switch Panel. PA system Panel. Battery backup Building floor plan 	-NA-	As above	-NA-
		-NA-	As above	-NA-
		-NA-	As above	-NA-
		-NA-	As above	-NA-
20	Special Fire Protection System for	-NA-	As above	N/A
20	the Protection of special Risk, if any:	(Part-IV) the nu	nber of occupant load cor	nes out to app

Covered area of the eating establishment is 130m² and as per NBC (Part-IV) the number of occupant load comes out to approx. 72 persons (130/1.8=72.22). Thus, the capacity is 51 which is covered under DFS Act 2007, Rules, 2010. Subsequently inspection of Eating House is carried out as per NBC (Part-IV).

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection. The Main Building has been issued FSC by this department vide letter No. F.6/DFS/MS/Mixed/SZ/2023/29 dated 18/12/2023.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/EH/2021/SZ/225 dated 10/09/2021, renewal under rule 37 of Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

Director My Jan Sir, E.T. Letter 5

Auf for your sing. pr.
Suman
04/09/2

Worded of Polary