

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 336

Dated...1.5./.1.0/2024

FIRE SAFETY CERTIFICATE

Restaurants Ltd. at E- 4, LSC, Masjid Moth, Greater Kailash -II, New Delhi - 110048 comprised of Basement (Storage), Ground, Mezzanine and One upper floor but (Restaurant running at Ground Mezzanine and One upper floor) owner/occupied by M/s Speciality Restaurants Ltd. was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2018/SZ/1301 Dated 05/06/2018 in the name of "M/s Mainland China". The premise was re-inspected by the officer concerned of this department on 07/10/2024 in the presence of Mr. Kajal Bishwas (Manager) of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" and Validity upto 31/03/2027 in accordance with rule 36 unless renewed/under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 15/10/2024 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

 The Joint Commissioner of Police, 1st Floor, P.S Defence Colony, New Delhi 110049 (Ref. MHA Portal ID 2024092514759 dated 25/09/2024)

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

 All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

 The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of

UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

7. The Basement shall be used strictly as per BBL.

1		W/29	7/5		
1		ON REPORT	आज़ादा अमृत	_{महोत्सव}	
1	Name & Address of the Building	M/s Speciality I Masjid Moth, G	Restaurants Ltd. at 1 reater Kailash -II,	E- 4, LSC, New Delhi.	
2	Type of Occupancy	Eating House at Ground Mezzanine Plus One Upper Floor Only)			
3	Building Comprised of	Basement, Ground + Mezzanine floor + one upper floor			
	Two of Coop	Renewal			
4	Type of Case Details of Previous NOC	F6/DFS/MS/EH/2018/SZ/1301 Dated 05/06/2018			
5		for the name of "Ms Mainland China Restaurant"			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	07/10/2024			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Kajal bishwas (Manager)			
10	Year of construction	2005			
11	Applicant letter No.	MHA Portal ID 2024092514759 dated 25/09/2024			
S.No.		Old NOC	Provided at	Remarks	
~	Prevention and Fire Safety U/R 33	requirements	Site	MR/NM	
1	Access to Building.		233 1		
-	Road width	4.5 mtr	6mtr	MR	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of	exits.	बुल्ह्यु । जन्मी प्रकार		
	Number of Staircase				
	Upper floors.	Required	02 nos	MR	
	Basement floor.	Required	02 nos	MR	
	Width of Staircase			19	
	Upper floors	Required	1.25m each	Old case	
	Basement floor	Required	1.25m each	Old case	
1 -5	Protection of exits				
	Fire check door	N/A	N/A	N/A	
200	Pressurization	N/A	N/A	N/A	
Si-	No. of continuous staircase to terrace	One	One	MR	
1	Width of corridor	N/A	N/A	N/A	
- 76	Door size	Required	1.25mtr (Two)	MR	
3	Compartmentation.	and the state of t			
	Fire check door.	N/A	N/A	N/A	
1	Sealing of electrical shafts.	Required	Provided	MR	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
1 2	Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.				
-	Basement	30АСРН	Exhaust fan Provided	MR	
- 1	Upper floors	12 ACPH	Exhaust fan Provided	MR	
5	Fire Extinguishers.	TE POIL	1 Edward Interviolet		
3		OO No.	LONG	MR	
-	Total numbers	08 Nos ABC/CO ₂	12Nos	MR	
	Types ISI Marking	ISI marked	ABC & CO ₂ Provided	MR	
-	Hirst Aid Hose Reels.	131 marked	Tiovided	WIR	
6	Total numbers on each floor.	One	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
1	Nozzle Diameter	5mm	Provided	MR	
7	Automatic fire detection & alarming s				
1 /	Type of detectors	Required	Smoke / heat	MR	

	W/3	gunthitt at	He souther to a	ते महोत्र
	Location of Main Panel	Required	Ground Floor	M
	Location of Repeater Panel Alternate source of power	N/A	N/A	N/
	Hooter's location	Required	Provided	M
	The state of the s	Required	Provided	M
	MOEFA	Required	Provided	M
	Public Address System	Required	Provided	MI
0	Automatic Sprinkler System		Tiovided	IVII
	Basement	Required	Provided	MI
	Ground floor & upper floor	Required	Provided	MF
	Sprinkler above false ceiling	N/A	NA	MF
1	Internal Hydrants.	Landings Party	INA	N/A
	Size of Riser/Down-comer	100 mm	Provided	100
	Number of Hydrant per floor	One	Provided	MR
	Hose box.	One		MR
2	Yard Hydrants.	Olic	Provided	MR
	Total number of hydrants.	N/A	NT/A	27/4
	Hose box.	N/A	N/A	N/A
3	Pumping arrangements.	IVA	N/A	N/A
	Ground Level			
	Discharge of main pump.	N/A	N/A	NT/A
	Head of main pump.	N/A	N/A N/A	N/A
	Number of main pumps.	E TOTAL CONTRACTOR OF THE PARTY		N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A N/A	N/A N/A	N/A
	Terrace Level	N/A	N/A	N/A
	Discharge of pump.	450 LPM	Provided	1 m
	Head of pump.		Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
	19 HT) 74 H 2 L F _ \$20 L 22 U.	Required	Provided	MR
14	Captive water storage for fire fighting.	N/A	N/A	N/A
	Underground tank capacity. Draw-off connection.	N/A N/A	N/A	N/A N/A
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	Required	15,000 ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
16	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A Paguired	N/A Provided	N/A
Tenn	Fireman's switch.	Required Required	Provided	MR MR
	Lift signage.	Required	Provided (DG set)	MR
17	Standby Power Supply	Required	. To trace (Dec set)	IVIK
18	Refuge Area	N/A	N/A	N/A
18		The same of the sa	the state of the s	THE RESIDENCE OF THE PARTY OF T
18	Total area	N/A	N/A	N/A
17	Location			N/A
19		N/A N/A N/A	N/A N/A N/A	N/A N/A





R	Battery backup.	N/A	N/A	N/A
R	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the	27/1	- 1122	IVA
	Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 406 dated 23/09/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2018/SZ/1301 Dated 05/06/2018 for the name of "Ms Mainland China Restaurant", renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (South) CFO (HQ) ts approved, F.T. Letter in problép for your synature el