

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-1 10001

No.F.6 DFS/MS/School/2024/SZ/1077

Dated: 29/10/2024

FIRE SAFETY CERTIFICATE

Certified that the MCPS Harijan Basti located at Rajokari, New Delhi 110038 Comprised of Ground floor only owner/occupied by Municipal Corporation of Delhi was issued Fire Safety Certificate by this department F6/DFS/MS/School/2021/SZ/861 Dated 21/10/2021. The said premise was re-inspected by officer concerned of this department on 10/10/2024 in presence of the Mrs. Lalita Rani (Principal) the school and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and that the building is fit for occupancy class "Educational Building Group - B" with effect from 29/10 / 2024 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Dalhi Fire Service Rules 2010.

Issued on 29/10.2024 at New Delhi by

DIRECTOR DIRECTOR ELHI FIRE SERVICE

Copy to: -

1. The Principal, MCPS Harijan Basti located at Rajokari, New Delhi 110038

2. The Director of Education, MCD, Civic Centre, Minto Road, New Delhi-110002

Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

_	INSPECT	TION REPORT		
1	Name & Address of the Building	M.C Primary School, Harijan Basti, Rajokari, New Delhi 110038		
2	Type of Occupancy	Educational, Group-B (School)		
3	Building Comprised of	Ground floor only		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/School/2021/SZ/861 Dt. 21/10/2021		
		DOE Circular 01/03/2011		
6	Fire Safety Directives Letter No	10-10-2024		
7	Date of Inspection	Sh. Rajesh Kumar, ADO (BCP)		
9	Name of the Inspecting Officers Name & Designation of Officers	Mrs. Lalita Rani (Principal)		
	from the building side	1982	with the second	
10	Year of construction	Outdoor diary No	7525 Dated 08/10/2024	
11 S. No	Applicant letter No. Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirement	Provided at Site	Remarks MR/NMI
1	Access to Building.		School is 100 (length of hose)	MR
1	Road width	6 mtr	away from road	(old case)
	Gate width	-NA-	NA	-NA-
	Width of internal road	-NA-	-NA-	-NA-
	Many Control of Contro	-100		
2	Number, width, type & arrangement of exits.			NTA
	a) Number of Staircase	-NA-	-NA-	-NA-
	Upper floors. Basement floor.	-NA-	-NA-	-NA-
	b) Width of Staircase		-NA-	-NA-
	Width of Staircase Upper floors	-NA-	DA BORE	-NA-
	> Basement floor	-NA-	-NA-	
	a de la compresenció de la compr		NA.	-NA-
	c) Protection of exits > Fire check door	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	> Pressurization	-NA-	-NA-	
	d) No. of continuous staircase to terrace	-NA-	-NA-	-NA-
	e) Width of corridor	1.0 m	Provided	MR
	f) Door size	prespectal		
3	Compartmentation.	100		274
		-NA-	-NA-	-NA-
	Fire check door.	-NA-	-NA-	-NA-
	Sealing of electrical shafts.	-NA-	-NA-	-NA-
	Fire rating of shaft door.	-NA-	-NA-	-NA-
	Water curtain	-NA-	-NA-	-NA-
	Fire dampers.			NIA
4.	Smoke Management system.	-NA-	-NA-	-NA-
	Basement	-NA-	-NA-	-IVA-
	Upper floors			MR
5.	Fire Extinguishers.	03 No's	Provided	MR
	Total numbers	ABC / Co2	ABC Type	MR
	• Types	ISI mark	Provided	MIK
	ISI Marking			-NA-
6.	First Aid Hose Reels.	-NA-	-NA-	-NA-
V	Total numbers on each floor.	-NA-	-NA-	
	Length of hose-reel hose. Nozzle Diameter	-NA-	-NA-	-NA-
	Automatic fire detection & alarming system.			

		-NA-	-NA-	-NA-
	Type of detectors	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
	 Alternate source of power 	-NA-	-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8.	MOEFA		-NA-	-NA-
9.	Public Address System	-NA-	-110	
10.	Automatic Sprinkler System	NA	-NA-	-NA-
	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	-NA-
	 Sprinkler above false ceiling 	-NA-	- (3)3-(1-)	
11.			-NA-	-NA-
	 Size of Riser/Down-comer 	-NA-	-NA-	-NA-
	 Number of Hydrant per floor 	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	
12.	Yard Hydrants.		-NA-	-NA-
	Total number of hydrants.	-NA-		-NA-
	Hose box.	-NA-	-NA-	1,11
13.	Pumping arrangements.			
15.	Ground Level		314	-NA-
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	> Jockey Pump output.	-NA-	-NA-	-NA-
	 Jockey Pump head. 	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level		NIA	-NA-
	Discharge of pump.	-NA-	-NA-	-NA-
	➤ Head of pump.	-NA-	-NA-	-NA-
	➤ Power supply.	-NA-	-NA-	-NA-
	Auto starting of pump.	-NA-	-NA-	-NA-
14.	Captive water storage for fire fighting.			211
	Underground tank capacity.	-NA-	-NA-	-NA-
	> Draw-off connection.	-NA-	-NA-	-NA-
	> Fire Service Inlet.	-NA-	-NA-	-NA-
	> Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	-NA-	-NA-	-NA-
5.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.			<u> </u>
0.	Pressurization of lift shaft.	-NA-	-NA-	-NA-
l N	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
	UL NOON SE	-NA-	-NA-	-NA-
	Lift signage.			112011
7.	Standby Power Supply	-NA-	-NA-	-NA-
8.	Refuge Area	-NA-	-NA-	-NA-
	Total area		MISSARE	
	Location	-NA-	-NA-	-NA-
).	Fire Control Room.			1
	 Detector system panel. 	-NA-	-NA-	-NA-
			-NA-	-14

_	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/School/2021/SZ/861 Dt. 21/10/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (SD

ed, f.f. tetter in portupe syndruse of