

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6 DFS/MS/School/2024/SZ/1103

Dated: 08/11/2024

FIRE SAFETY CERTIFICATE

Certified that the Holy Child Auxilium School located at Poorvi Marg, Vasant Vihar, New Delhi- 110057 comprised of Ground plus two upper floor owner/occupied by Holy Child Auxilium School, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2021/SZ/889 Dated 29/10/2021. The said premise was re-inspected by officer concerned of this department on 30/10/2024 in presence of Sr. Maria Goretti Ekka and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational Building Group - B" with effect from OS/II / 2024 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on 08/11-2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Principal, Holy Child Auxilium School, Poorvi Marg, Vasant Vihar, New Delhi.

2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 2. All the staff members must know the correct method of operation of firefighting system.
- This certificate cannot be treated as regularization of unauthorized construction, if any.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



1	Name & Address of the Building	Holy Child Auxilium School, Poorvi Marg, Vasant Vihar, New Delhi- 110057.			
2	Type of Occupancy	Educational, Group-B (School)			
3	Building Comprised of	Ground + Two upper floors.			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/DFS/MS/School/2021/SZ/889 Dated 29/10/2021			
6	Fire Safety Directives Letter No	F6/MS/DFS/2005/420 Dated 04/07/2005			
7	Date of Inspection	30/10/2024			
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Name & Designation of Officers from the building side	Sr. Maria Goretti Ekka			
10	Year of construction	2006			
11	Applicant letter No.	Outdoor diary no 5327 dated 16/08/2024			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMI	
1.	Access to Building.		Land Bath	f 44	
1 10	Road width	9 mtr	9 mtr	MR	
y Vi	Gate width	5 mtr	5 mtr	MR	
	Width of internal road	-NA-	-NA-	-NA-	
	And Market Control of the Control of	5 FAC 250	-14/4-	-IVA-	
2.	Number, width, type & arrangement of ex	its.			
40	a) Number of Staircase	03 Nos	Provided	MR	
	> Upper floors.	(CO. C.	-NA-	-NA-	
	➤ Basement floor.	-NA-	-NA-	-MA-	
	b) Width of Staircase > Upper floors	1.5 m /0.75 m	1.50 m x 2 each & 1.45 m	MR	
	➤ Basement floor	-NA-	-NA-	-NA-	
	c) Protection of exits	-in-			
	Fire check door	-NA-	-NA-	-NA-	
	> Pressurization	-NA-	-NA-	-NA-	
-476	d) No. of continuous staircase to terrace	Required	01 Nos	MR	
310	e) Width of corridor	1,50 m	Provided	MR	
	n Door size	l m	Provided	MR	
3.	Compartmentation.				
	Fire check door.	-NA-	-NA-	-NA-	
	 Sealing of electrical shafts. 	-NA-	-NA-	-NA-	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
1	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.	20 ACDIT	NA.	T NA	
	Basement	30 ACPH	-NA-	-NA-	
, Au	Upper floors	12 ACPH	-NA-	-NA-	
5.	Fire Extinguishers.	, I	2031	MR	
100	Total numbers	Required	20 Nos		
	Types	ABC / CO2 ISI marked	ABC & CO2 Provided	MR MR	
	ISI Marking	131 marked	Tiovidea	MIC	
6.	First Aid Hose Reels.	02 No.	Provided	MR	
	Total numbers on each floor.	02 Nos 30 m	Provided	MR	
	Length of hose-reel hose. Nozzle Diameter	5mm	Provided	MR	
7.	Automatic fire detection & alarming system.	T	II will be to the		

N/16

	Type of detectors	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8.	MOEFA	-NA-	Provided	-NA-
9.	Public Address System	-NA-	Provided	-NA-
0.	Automatic Sprinkler System			
	Basement	-NA-	-NA-	-NA-
	 Upper floors 	-NA-	-NA-	-NA-
	 Sprinkler above false ceiling 	-NA-	-NA-	-NA-
1.	Internal Hydrants.			
	Size of Riser/Down-comer	NA	100 mm	NA
	Number of Hydrant per floor	-NA-	02 Nos	-NA-
	Hose box.	-NA-	02 Nos	-NA-
2.	Yard Hydrants.			
	 Total number of hydrants. 	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
3.	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	➤ Jockey Pump output.	-NA- ,	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	> Standby Pump output.	-NA-	-NA-	-NA-
	➤ Standby Pump head.	-NA-	-NA-	-NA-
	➤ Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			
	Discharge of pump.	450 LPM	450 & 180 LPM	MR
	➤ Head of pump.	40 mtr	Provided	MR
	➤ Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
4.	Captive water storage for fire fighting.			
	Underground tank capacity.	-NA-	-NA-	-NA-
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	 Overhead tank capacity. 	10,000 ltrs	Provided	MR
5.	Exit Signage.	Required	Provided	MR
5.	Provision of Lifts.			
-	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.		ASSESSED.	-NA-
		-NA-	-NA-	
	Lift signage.	-NA-	-NA-	-NA-
7.	Standby Power Supply	-NA-	-NA-	-NA-
3.	Refuge Area			172.273
	Total area	-NA-	NA-	-NA
	Location	-NA-	-NA-	-NA-
	Fire Control Room.			





	Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

The fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules, the FSC issued vide letter No. safety F6/DFS/MS/School/2021/SZ/889 Dated 29/10/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

approved Fit. Letter is party too you