

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/2024/ 376

Dated : 14/11/2024

FIRE SAFETY CERTIFICATE

Certified that Ivory Fusion Bar (A Unit of Starshine Leisure Pvt. Ltd.) located at 2nd floor, F-60, Malhotra Bulding, Connaught Place New Delhi in a building comprised of Ground +2 upper floors but restaurant is running at 2nd floor only. The FSC was earlier granted by this department to vide letter No.F6/DFS/MS/EH/2021/NDZ/29 dated 04/02/21 for the name & style Ms the Station Bar. Now, the premises was re-inspected by the officers concerned of this department on 08/11/24 in the presence of Mis. Komal, Manager and found that the said restaurant premises has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant premises is fit for occupancy class Assembly Building (Group D) (Restaurant) at second floor only and valid up to the period of three year from the date of issue in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below;

Issued 14/11/2024 New Delhi by.

DIRECTOR Delhi Fire Service

Copy to:-

1. The Chief Architect, NDMC, Palika Kendra, New Delhi. To kindly ensued the occupancy and deviation in construction if any.

2. The Dy. Commissioner of Police(Lic), Ist floor, PS Defence Colony, New Delhi

Online ID no. 2024092614865 dated 17/10/24.

 The Manager, Ivory Fusion Bar (A Unit of Starshine Leisure Pvt. Ltd.) located at 2nd floor, F-60, Malhotra Bulding, Connaught Place New Delhi.

Condition for the validity of fire safety certificate

1. This FSC is valid for restaurant at second floor only

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any

deviation in construction etc. shall be verified from authority concerned.

This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any

 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

 The means of escape such as exits, corridor, etc shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any flammable for interior decoration shall strictly be prohibited.

N/15

INSPECTION REPORT 1. Name & address of the building

Ivory Fusion Bar (A Unit of Starshine Leisure Pvt.

Ltd.) 2nd floor, F-60, Malhotra Building, New

2. Type of occupancy:-

Assembly Building Group-D Ground .+2 Upper floors,

Restaurant running at 2nd floor only

Type of case:-

Renewal

4. Details of previous FSC:-

F6/DFS/MS/EH/2021/NDZ/29 dated 04/02/21.

5. Fire safety directives No.-

N/A

6. Date of inspection:-7. Name of the inspecting officer:-

08/11/24 Sh. Rajinder Atwal, DO (CD) & Sh. Ravinder Singh, ADO (CC)

8. Name & designation of officer From the building side:-

Mis Komal, Manager

9. Year of construction:-

Heritage building 1960

ID no. 2024092614865 dated 17/10/24.

.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
	Access to Building			MR	
	1) Road width	09	16 mtr	N/A	
	2) Gate width	N/A	N/A	N/A	
1	2)Width of internal road	N/A	N/A	N/A	
-	Number, Width Type & Arrangement of Exits				
2.	A. Number of staircases			MR	
	1. Upper floors	02	02	N/A	
	2. Basements	N/A	N/A	14/71	
	B. Width of staircase		100 1 0 1 25	MR(old	
	1. Upper floors	1.35mt & .80 mtr	1.20mtr & 1.35 mtr	case)	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits			N/A	
	1. Fire check door	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A 01	
	D. No. of continuous	01	01		
	staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor F. Door size	2 mtr & 1.0mtr	provided	MR	
3.	Compartmentation			N/A	
	1) Fire check door	N/A	N/A	N/A	
	Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	14/74	
4.	Smoke Management System	1500	I NI/A	N/A	
	1) Basements	N/A	N/A Exhaust fan	MR	
	2) Upper floors	12 a/c per hour	EXTIBUSE IAII	IVIIX	
5.	Fire Extinguishers) (D	
	1) Total numbers	06 Nos.	06 Nos.	MR	

	2) Types N16	ARC & CO2	ABC & CO2	
	3) ISI marking	Required	Provided	MR
	First-Aid Hose Reel	Required	Hoyaca	
6.	1) Total number of each floor	01	Provided	MR
		30 mtr.	30 mtr.	MR
	2) Length of hose reel hose	05 mm	05 mm	MR
	3) Nozzle diameter		103 11111	IVIK
	Automatic Fire Detection & Alarm	Required	Provided	MR
	1) Type of detectors (smoke)	second floor	Provided	MR
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel		Provided	MR
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Required	A STATE OF THE PARTY OF T	- CANADAN AND AND AND AND AND AND AND AND A
	MOEFA	Required	Provided	MR
	Public Address System	N/A	N/A	N/A
0.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
1.	Internal Hydrants	r		Name of the last o
	1) Size of riser/down-comer	100mm	100mm	MR
	2) Number of hydrants per floor	01	Provided	MR
_	3) Hose box	01	Provided	MR
12	Yard Hydrants			Topic and
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
12	Day of Contract Contr			,
13.	Pumping Arrangement	\	1	
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head h) Auto starting/Manual	N/A N/A	N/A	N/A
	stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM /	1
	b) Head of pump	430 LPM 40 mtr.	450 LPM 2	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fire Fig		FIOAIGEG	MR
	Under ground tank capacity	N/A	N/A	I NI/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	Required	Provided	N/A
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	10,000 ltr.	10,000 ltr. v	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	Roquiled	Tiovided	MR
		NVA		
	a) Pressurization of lift shaft b) Pressurization of lift lobby	N/A	N/A	N/A
		N/A	N/A	N/A
	 c) Communication in lift car 	N/A	N/A	N/A

	d) Fireman's switch	N/A	N/A	N/A
	77 710 1	N/A	N/A	N/A
	Stand by Power Supply	Required	Provided	MR
7.		N/A	N/A	N/A
18.	Refuge Area		NIA	N/A
	Total area location	N/A	N/A	N/A
	I Doom	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	*M.E.C	
		N/A	N/A	N/A
	b) Flow switch panel	14.000.000.00	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	IVA	(HPANOSPES)
			NIA	N/A
	e) Building floor plan	N/A	N/A	NA
	c) Building noon p	building not protection of special Risk, if		
0.	Special Fire Protection System for Protection of special Risk, if any: The fire protection systems provided in the building were random that the time of inspection.			

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter F6/DFS/MS/EH/2021/NDZ/29 dated 04/02/21, under rule 35(6) of the

Signature of the Inspecting Officer

Name :- Ravinder Singh Designation :- ADO (CC)

checked and found functional at the time of inspection.

Signature of the Inspecting Officer

Designation :- DO (CD)

Delhi Fire Service rules 2010 is recommended for approval.