

c/109

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/School/2021/ 223

Dated:-19/04/2021

To,

The Principal,  
Modern School,  
Barakhamba Road,  
New Delhi – 110001.

**Sub: Regarding grant of fire FSC in r/o Modern School, Barakhamba Road, New Delhi.**

Sir,

This has reference to your E-mail< principal@modernschool.net > dated 24.03.2021 on the subject cited above. In this regard, it is to inform you that the Platinum Jubilee Block, S.S.Block, HLL Hall, & Main building were inspected by officers concerned of this department on 07.04.2021 in the presence of Sh. Rishi Panday and the following shortcomings were observed in main building .

1. Only one staircase is continuous to 2<sup>nd</sup> floor , alternate staircase is also required up to 2nd floor of Main block.
2. Terrace pump of 450 LPM and overhead water tank of 10,000 liter is not provided at Main block
3. First aid hose reel is not provided in Main block.

In view of above shortcomings, the application for renewal of FSC is rejected. The occupancy in the building in absence of requisite fire safety arrangements shall be at risk and liability of owner /occupier. Further, statutory authority / building sanctioning authority may take necessary action as deemed fit

Yours faithfully

  
16/4/21

(Dr. S.K. Tomar)  
Dy. Chief Fire Officer  
Delhi Fire Service

Copy to:-

The Director (Education),  
Govt. of NCT, Old Sectt.  
Delhi - 54.

  
16/4