GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2021/ 354

Dated: \ 9/7/2/

To,

The Principal, Ojas Shikshan Sansthan, A-7, Sector-17, Rohini, Delhi-110085.

Sub: Issue of FSC in r/o Ojas Shikshan Sansthan, A-7, Sector-17, Rohini, Delhi-110085.

Sir.

Kindly reference to online e-mail dated 05.04.2021 received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 08.06.2021, in presence of Sh. Pawan Kumar (Chairman) to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for renewal of FSC is rejected under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. Terrace Fire pump with capacity 450 LPM provided but not functional.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

Yours faithfully

(Dhrampal Bhardwaj) Dy. Chief Fire Officer Tel;-01123414250

O(c