GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

02/08/2021

NO. F6/DFS/MS/SZ/2021/ 390

DATED: 02 /03/2021

To,

The Principal, Sarvodaya Kanya Vidhalaya No 2, Palam Village, New Delhi – 110045

Subject: - Renewal of Fire safety in r/o Sarvodaya Kanya Vidhalaya No 2, Located at Palam Village, New Delhi – 110045.

Sir,

Please refer to letter no. Email Dated 07/07/2021 on the subject mentioned above. In this connection it is submitted that that the above said premises was visited by the officer concerned of this department on 13/07/2021 to see the compliance of the shortcomings communicated vide this office letter no. F6/DFS/MS/School/2018/SZ/1941 dated 10/05/2018 and found that the shortcomings are still not complied. You are requested to comply the shortcomings under intimation with this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,

(Sunil Chaudhary) Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

1. Directorate of Education Old Secretariat Delhi – 110054

C-23

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F6/DFS/MS/School/2018/SZ To.

Dated: 10/05/18

Head of School, Sarvodaya Kanya Vidhalaya No.2, Palam Village, New Delhi-110045.

Subject:- Renewal of Fire Safety Certificate from Fire safety point of view in r/o Sarvodaya Kanya Vidhalaya No.2, Palam Village, New Delhi-110045.

Madam,

This is in reference to your letter no. SKV/PV/ND/2018/1439 dated 5.2.2018 on the subject cited above. In this connection, it is to inform you that above said school building have been inspected by the officer concerned of this department on 6.4.2018 in presence of Mrs. Pramila Varshnaya (HOS) & Sh. Gajraj Singh (Estate manager) to see workability of fire fighting system provided therein.

During the course of inspection following shortcomings have been observed:

- 1. Fire pump at terrace level is provided but not operational.
- 2. Water storage tank for firefighting at terrace level found empty.

In view of the above mentioned shortcoming fire safety certificate cannot be granted at this stage. You are advised to rectify above shortcomings under intimation to this department for taking further necessary action.

Yours Faithfully,

(Vipin Kental)
Chief Fire Officer

Copy to:-

1. The Director (Education), GNCT of Delhi, Old Secretariat, Delhi-110054.