

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/WZ/School/2021/ 454

Dated: 01/09/2021

To,

The Principal,  
BVM Model School,  
Rajiv Nagar, Begumpur,  
Opp. Sec-22, Rohini,  
Delhi-110086.

**Sub:** Issue of FSC in r/o BVM Model School, Rajiv Nagar, Begumpur, Opp. Sec-22, Rohini, Delhi-110086.

Sir,

Kindly reference to online e-mail dated 12.07.2021 received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on **16.08.2021**, in presence of **Smt. Kanta Sharma (Principal)** to ascertain the availability and operability of the fire prevention and fire safety measures. The following shortcomings were observed:

1. The width of staircase is 1.8m, 1.3m & 1.25mtr against the required width of staircases of 1.5 mtr. Half portion of building on 2<sup>nd</sup> floor have single exit only.
2. Terrace Fire pump with capacity 2 x 450 LPM provided but not functional.

In this regard as stipulated in sub Rule (5) of Rule 35 of DFS Act-2007 & Rules 2010 it is advised the applicant to apply with a fresh application for grant of fire safety certificate under sub-rule (2) on Form "I" and it shall be accompanied with a certificate from the architect and owner or occupier that all the fire prevention and fire safety measures are duly complying with the requirements as communicated under sub-rule (4) above, for further consideration in this regard. The web links for DFS Act-2007/ Rules 2010 & Form "I" are as under:

[http://www.delhi.gov.in/wps/wcm/connect/doit\\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit\\_fire/FIRE/Home/Forms](http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms)

Yours faithfully

  
(Anu Garg)  
DIRECTOR

Ph; 011-23414000

SLC  
PM