

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2021/SZ/ 570

Dated: 22/09/2021

To

The Principal,
 Kendriya Vidyalaya Sector-2,
 R.K Puram, New Delhi 110022

Sub: Regarding issue of Fire Safety Certificate (FSC) in r/o Kendriya Vidyalaya Sector 2, R.K. Puram, New Delhi 110022

Sir,

This is in reference to F. No KVS/Sector-2/RKP/2021-22/228 dated 23/08/2021 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 17/09/2021 in the presence of Sh. Awadhesh Dubey (Principal) and observed that the shortcoming intimated vide letters of even nos 171 dated 06/03/2020 has yet not been complied. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Encl: As above

(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Sun

Copy to:-

1. Dy. Director (Education) Kendriya Vidyalaya Sangthan, Delhi Region, JNU Camp New Mehrauli Road, New Delhi -110067

G-13

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/School/2020/SZ/ 171

Dated: 6/3/2020

To

The Principal,
Kendriya Vidyalaya Sec-2,
R.K.Puram, New Delhi-110022

Sub.: Reg. Renewal of FSC.

Sir,

This is in reference with your letter No. FN/KV/Sector-2/RKP/2019-20/172 Dated 19/11/2019 received through outdoor diary No. 26018 dated 25/11/2019 on the subject cited above. In this connection, the school premise was re-visited by officer concern of this department on 19/02/2020 to verify the status of fire prevention and fire safety measures already provided therein in your presence. During the inspection, the shortcomings observed are as below: -

1. Fire Extinguisher found empty and required 20nos provided 15nos.
2. Hose-reels found non-functional.
3. Terrace level pump found non-functional.

In view of above shortcomings, renewal of FSC cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department for further consideration in the matter.

Yours faithfully,


(Atul Garg)

Director
Delhi Fire service



Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.