GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE : NEW DELHI - 110001

No. MIDFS/175/204/HospHel/1888 Dated: 28/09/204

To,

The Medical Superintendent, Acharya Bhikshu Hospital, Moti Nagar, New Delhi-110015.

Subject: Inspection report in respect of Acharya Bhikshu Hospital, Moti Nagar, New delhi-15.

Sir,

This has the reference to the directions issued by GNCT of Delhi for inspection of the Govt. Hospitals. In this regards, it is submitted that the aforesaid hospital building was re-inspected by the officers concerned of this department on 29.09.2021 in the presence of Sh. Rajiv, A.E. (Civil) to check the status of the shortcomings issued by this department vide letter No. F.6/DFS/MS/2021/WZ/Hospital/794 dated 07.04.2021. The status of the shortcoming is as under: -

S. No.	Shortcomings	Status
1.	Fire Check door is removed in staircase at some places of basement & upper floor.	Provisioning of FCD is still under progress

In addition to the above, following shortcomings were also observed at the time of inspection: -

- 2. Fire Alarm system and Detection System is not working at some places.
- 3. Ventilation system is not working in the Basement floor.

In view of the above mentioned shortcomings, your request for renewal of Fire Safety Certificate is rejected. Till such time, occupancy of hospital building is at your risk & responsibility.

Yours faithfully,

(Dharampal Bhardwaj) Dy. Chief Fire Officer, West Zone

Copy to:-

- Sh. Anil Govil Assistant Engineer (E) HSW 4, PWD HMED South West Janak Puri Super Speciality Hospital, C-2B, Janakpuri, New Delhi -110058
- 2. Executive Engineer, PWD (Electrical) HMED (SW), DAP Lines, Vikas Puri, New Delhi