

C31

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001.

No.F6 /DFS/MS/EH/NDZ/2021 /429

Dated: 01/10/2021

To

The Joint Commissioner of Police,
Office of Joint commissioner of Police: Licensing,
1st Floor, P S Defence Colony, New Delhi.

Sub: Regarding grant of Fire Safety Certificate in r/o M/s Mc Donald's Family Restaurant,
II/1888-1889, Chandni Chowk, Delhi.

Sir,

This has reference to email letter dated 01.09.2021 on the subject cited above. In this connection above said restaurant was inspected by officer concerned of this department on 27.09.2021 in the presence of manager and it was observed that the building is comprised of ground floor. The following shortcomings were observed during the inspection.

1. Hose reel found non functional.
2. Hydrant outlet and hose box in down-comer systems found non functional.
3. Fire pump found not functional.
4. Sprinkler system provided for LPG bank found non functional.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Tel: 011-23412025



Copy to:-

The Manager,
M/s Mc Donald's Family Restaurant, II/1888-1889, Chandni Chowk, Delhi.