GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/WZ/2021/ 51

Dated: 02/02/2011

To

The Principal Queen Mary's Middle School, A-Block, Sector-25, Rohini, Delhi-110085.

Sub: - Regarding issuance of fire safety certificate in r/o Queen Mary's Middle Sec-School, 25, Rohini Delhi-110085.

Sir.

Kindly reference to online mail dated 22.12.2020, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 18.01.2021, in presence of Mr. Brij (Care taker) to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for issue of FSC is rejected under sub rule (4) of Rule 35 of DFS Rules-2010 due to following reason:

- 1. Temporary rooms founds constructed on terrace of 3rd floor.
- 2. Terrace door not opening toward terrace.
- 3. 4000 ltrs Over Head water captive tank provided against the required capacity of 10,000 ltrs.
- 4. Inspection ladder for tank inspection is not providing.
- 5. Fire System is not in working condition and fire hoses are in damaged condition.
- 6. Pump is not in working condition

In this regard as stipulated in sub Rule (5) of Rule 35 of DFS Act-2007 & Rules 2010 you may apply with a fresh application for grant of fire safety certificate under sub-rule (2) on Form "I" and it shall be accompanied with a certificate from the architect and owner or occupier that all the fire prevention and fire safety measures are duly complying with the requirements as communicated under sub-rule (4) above, for further consideration in this regard. The web links for DFS Act-2007/ Rules 2010 & Form "I" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rule#http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

Yours faithfully

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel;-01123414250

Chy