

e51

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2021/ 570

Dated: 14/10/2021

To,

The Principal,
Govt. Co-ed, Sr. Sec. School,
Sector-15, Rohini,
Delhi-110089.

Sub: Issue of FSC in r/o Govt. Co-ed, Sr. Sec. School, Sector-15, Rohini, Delhi-110089.

Sir,

This is in reference to your online e-mail dated 09.09.2021 on the subject cited above. The premise was inspected by the concern nominated authority of this department on **27.09.2021**, in presence of **Sh. Partap Singh (Estate Manager)** to ascertain the availability and operability of the fire prevention and fire safety measures. The following shortcomings were observed:

1. 5000 ltrs Over Head water captive tank provided against the required capacity of 10,000 ltrs.
2. Nozzles found missing on Hose reel.

In this regard as stipulated in sub Rule (5) of Rule 35 of DFS Act-2007 & Rules 2010 it is advised the applicant to apply with a fresh application for grant of fire safety certificate under sub-rule (2) on Form "I" and it shall be accompanied with a certificate from the architect and owner or occupier that all the fire prevention and fire safety measures are duly complying with the requirements as communicated under sub-rule (4) above, for further consideration in this regard. The web links for DFS Act-2007/ Rules 2010 & Form "I" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doiit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/
http://www.delhi.gov.in/wps/wcm/connect/doiit_fire/FIRE/Home/Forms

Yours faithfully


(Atul Garg)
DIRECTOR

Ph; 011-23414000

bc
ny