GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



F-6/DFS/MS/EH/SZ/2021/ 476

Dated: 01/11/2021

Sh. Saurabh Sharma (Owner),

M/s. Afolabi Kitchen and Bar, Plot No. R- 547,

New Rajender Nagar, Shankar Road, New Delhi- 110060.

Sub: - Regarding issuance of fire safety certificate in r/o M/s. Afolabi Kitchen and Bar, Plot No. R- 547, Third Floor, New Rajender Nagar, Shankar Road, New Delhi- 110060.

Please refer to online application ID 2021092822734 dated 01.10.2021 on the subject Sir. cited above. Above said eating house running at third floor of a building comprised of basement, stilt, ground plus three upper floors. In this connection it is to inform you that the above said assembly building (Restaurant & Bar) was inspected by the officer concerned of this department from safety point of view on 07.10.2021 in presence of Mr. Saurabh Sharma, Owner of the restaurant.

During the course of inspection it has been observed that fire safety arrangements such as fire extinguishers. First aid hose reels found provided, However the following shortcomings have been observed:-

- 1 Two staircases with width 1.50 mts. each are required.
- 2 Two exits with width 1.50 mts. each are required.
- 3 Fire Check Doors are not provided in kitchen.
- 4 Smoke ventilation not provided.
- 5 Smoke Detector found not provided.
- 6 MOEFA found not provided.
- 7 P.A system found not provided.
- 8 Internal hydrant system found not provided.
- 9 Required electrical fire pump capacity of 2280 LPM and standby diesel pump of 2280 LPM capacity along with jockey pump of 180 LPM
- 10 Terrace pump capacity 450 LPM is not provided.
- 11 Underground water tank requirement of 1,00000 lts capacity found not provided.
- 12 Overhead water Tank capacity 2,000 lts provided against requirement of 10,000 lts for firefighting is required.
- 13 Exit signages are not provided at the places mentioned during the inspection.

Keeping in view of above, fire safety certificate cannot be considered at this stage. You are requested to rectify the above said shortcomings for taking further necessary action in this matter.

Yours faithfully

Copy to:-

1. The Executive Engineer (Building), North MCD, Karol Bagh, Anand Parbat, New Delhi.