

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/WZ/2021/608

Dated: - 18/11/2021

To

The HOS,
M.C.P Boys School,
Mundka, New Delhi- 110041.

Sub.-: Regarding issuance of Fire Safety Certificate in r/o M.C.P. Boys School located at Mundka, New Delhi- 110041.

Sir,

Please refer to your E-mail/letter' dated 04.10.2021 on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in the presence of Sh. Ashok Kumar (Primary Teacher), on 08/11/2021 to check the fire safety arrangements provided in the building.

During the inspection, it was also observed that the school building is having two blocks. First block is comprised of ground & first floor served by single staircase having width 1.50 mts and second block is comprised of ground plus two upper floors served by three nos. of staircases having width 1.50 mts each. No fire safety arrangement found provided in the school building except fire extinguishers. Following fire safety arrangements are required: -

1. First aid hose reel at each floor in second block.
2. Terrace pump having capacity atleast 450 LPM for second block.
3. Overhead water storage tank capacity 10000 lts shall be provided exclusively for firefighting purpose in second block.

In view of above shortcomings, the application for issuance of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety measures shall be at the risk and liabilities of the owner/occupier.

Yours faithfully

(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

-for information please.