

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No.F6/DFS/MS/NDZ/2021/ 530

Dated:-22./11./2021

To

The Manager,  
M/S Hum Hindustani (Ved Pahoja Associates Pvt.Ltd),  
Subway B. S. Z. Marg, ITO, New Delhi.

Sub: Regarding issuance of FSC in r/o M/S Hum Hindustani (Ved Pahoja Associates Pvt.Ltd) located at Subway B. S. Z. Marg, ITO, New Delhi. Online ID No. 2021100623451 dated 06.10.21.

Sir,

This has reference to Online ID No. 2021100623451 dated 06.10.21, on the subject cited above. In this connection it is to inform you that the site was inspected by the officers concerned department on 08/11/2021 in the presence of Sh. Puran (Manager), and following shortcomings were observed:-

1. Alternate exit of 1.5 mtr is not provided and this should not be through kitchen.
2. First aid hose reel not provided.
3. Hydrant systems are not provided as per IS 3844/1989.
4. Overhead tank of 20000 ltr capacity is not provided.
5. Terrace pump of 450 LPM is not provided.
6. MOEFA is not provided.
7. Plan submitted with the application is incomplete and not signed by architect & owner/occupier.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings for further consideration in the matter.

Yours faithfully

(Atul Garg)  
DIRECTOR

Delhi Fire Service

Copy to :-

1. The Addl. Commissioner of Police (Lic.), Licensing Unit, Defence Colony, Police Station, New Delhi