

DF. n

c 203

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001**

No. F6/DFS/MS/GH/NDZ/2022/258

Dated: 04/04/2022

To

The Joint Commissioner of Police (Licensing),  
1<sup>st</sup> Floor, Police Station Defence Colony,  
New Delhi.

**Sub:** Regarding renewal of Fire Safety Certificate in respect of **M/s Adarsh Atithi Niwas Pvt. Ltd.**  
Located at **483, Haveli Haider Quli, Chandani Chowk, Delhi.**

Sir,

With reference to Email dated 16.03.2022 on the subject cited above, it is informed that the guest house was inspected by Assistant Divisional Officer (SPM) from this department on 28.03.2022 in the presence Mr. Ramdev Sharma (Owner) and it was observed that building is comprised of Ground + Mezz. + 03 upper floors. During inspection, following shortcomings were observed:-

1. Smoke Management System not provided properly.
2. Fire pump not in auto start mode.
3. Overhead tank exclusively for firefighting not provided.
4. Exit Signage not adequately provided.
5. Fire Safety Certificate will be considered only upto 2<sup>nd</sup> floor, please provide undertaking.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



**((Dr. S.K. Tomar))**

Dy. Chief Fire Officer

Tel: 011-23412025

3/1/22

**Copy to:-**

The Licensee,

M/s Adarsh Atithi Niwas Pvt. Ltd. Located at 483, Haveli Haider Quli, Chandani Chowk, Delhi.