

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/School/NDZ/2022/165

Dated:- 07/04/2022

To

The Executive Engineers (Bldg.)
East Delhi Municipal Corporation

Sub: Regarding issuance of FSC in r/o Tamil Education Sr. Sec School located at Mayur Vihar Phase-III, Delhi-92. (Online ID – 10098927 dated 31/3/2022)


Sir,

This has reference to joint inspection dated 05/04/2022 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 05/04/2022 in the presence of Mr. S.D Tomar, Ex. Engineer, EDMC & Mr. K.K Gupta, JE(C) and the following shortcomings were observed :-

1. One side building access is 5.65 mtr. provided instead of 6.0 mtr.
2. Stationary pump near under ground water tank i.e. One electric pump capacity 2280 LPM, one diesel pump of 2280 LPM and jockey pump of 180 LPM are not provided.

Hence, the Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings under the intimation to this department for further necessary action in this regard.

Yours faithfully



(Atul Garg)
Director
Delhi Fire Service

