

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F.6/DFS/MS/NDZ/2022/ 949

Dated 29.04/2022

To,

Sh. Vizeta Marchino,
Assistant General Manager,
Reserve Bank of India,
6, Sansad Marg, New Delhi.

Sub:- Regarding renewal of FSC in r/o Reserve Bank of India, 6, Sansad Marg, New Delhi.

Sir,

With reference to your letter No. ND SI & SU S/596/14.04.003/2021-22 dated 17/03/2022 on the subject cited above, it is to inform you that the site was inspected by the officers concerned department on 18/04/2022 in the presence of Sh. Vizeta Marchino, AGM and the following shortcomings were observed:-

1. Hose reel not covering entire area.
2. Some MOEFA found nonfunctional.
3. Pumps were not in auto mode provision.
4. Lift signages "not to use lift in case of fire" not provided.
5. Electric panel provided in basement is not protected with fixed fire protection system.
6. Flammable Plastic sheet used at terrace floor is required to be replaced with nonflammable sheets.
7. Trimming of trees is required for smoothly/freely movement of fire vehicles.

In view of above shortcomings, request for renewal of fire NOC is rejected. The occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit

Yours faithfully


(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:-

The Chief Architect, New Delhi Municipal Council, Palika Kendra, New Delhi.