

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/EH/NDZ/2022/315

Dated: 04.05.2022

To,

The Addl. Commissioner of Police (Licensing),
1st Floor, Police Station Defence Colony,
New Delhi.

Sub: Application for issuance of fire safety certificate in respect of **M/S HANDI CHHADEYAN DI**, located at Shop No.59, Municipal Market, Outer Circle Connaught Circus, New Delhi.

Sir,

This has reference to your online id no. **2022040205241** dated **02.04.2022** on the subject cited above. In this regard, it is to inform you that the site was visited by officer concerned of this department on dated 20.04.2022 in presence of **Manager** observed that shortcomings issued vide letter No.F.6/DFS/MS/NDZ/2021/560 dated 07/12/2021, have not been complied so far.

In view of above, FSC can't be issued till the compliance of all the shortcomings issued vide aforesaid letter.

Yours faithfully,

(Atul Garg)

DIRECTOR
Delhi Fire Service

Copy to:

1. The Manager,
M/S HANDI CHHADEYAN DI, Shop No.59, Municipal Market, Outer Circle,
Connaught Circus, New Delhi.

CS

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/NDZ/2021/ 560

Dated:- 7.11.2021

To

The Manager
M/S **HANDI CHHADEYAN DI**,
Located at Shop no. 59, Municipal Market,
Outer Circle Connaught Circus, New Delhi.

Sub: Regarding issuance of FSC in r/o M/S **HANDI CHHADEYAN DI**, at located at Shop no. 59, Municipal Market Outer Circle, Connaught Circus, New Delhi.

Sir,

This has reference to online ID No. 20211030255558 dated 30.10.21 on the subject cited above, it is to inform you that the site was inspected by the officers concerned department on 25/11/2021 in the presence of Sh. Santosh and the following shortcomings were observed:-

1. Single staircase of .75 meter is provided against the requirements of 02 staircase of 1.5 meter each.
2. One exit of 1.0 meter is provided at ground floor against the requirements of 02 exit of 1.5 meter each.
3. Fire extinguishers are not provided as per IS 2190.
4. First aid hose reel and hydrant system are not provided.
5. MOEFA is not provided.
6. Terrace pump of 450 LPM& Overhead fire water tank of 20,000 liter cap. are not provided.
7. Exit signages found inadequate.
Further, you have uploaded only section /elevation plans whereas building plans of restaurant having all details duly signed with Architect and Owner itself is also required to be uploaded.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings for further consideration in the matter.

Yours faithfully


(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to :-

The Joint Commissioner of Police (Lic.), Licensing Unit, Defence Colony
Police Station, New Delhi.