

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F.6/DFS/MS/2022/NDZ/ 1015

Dated 09/05/2022

To,

Mr. Kapil Sharma,  
Head –Administration,  
MBD House, Gulab Bhawan,  
6, B.S.Z. Marg, New Delhi – 110002.

**Sub:- Regarding renewal of FSC in r/o Gulab Bhawan, 6, Bahadur Shah Zafar Marg,  
New Delhi – 110002.**

Sir,

This has reference to your e-mail <kapil.Sharma@mbdgroup.com dated 21.04.2022 on the subject cited above, it is to inform that the site was inspected by the officers concerned of this department on 02/05/2022 in the presence of Sh. Kapil Sharma and the following shortcomings were observed: -

1. Fire check doors for compartmentation in front block found removed at some places.
2. Detectors are found removed at some places and in front block also and found non-functional.
3. MOEFA found nonfunctional and also to be extended in left out area.

In view of above, the request for renewal of shortcomings is rejected. The occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully

(Atul Garg)

**DIRECTOR**

Delhi Fire Service

Copy to :

The Commissioner, North, MCD, Civic Centre, New Delhi.