

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

C-29

No.F6/DFS/MS/School/SZ/2022/ 222

Dated: 13/05/2022

To

The Principal,
New Kalindi Public School,
J-36, Saurabh Vihar, Badarpur, New Delhi-44.

Sub:- Regarding renewal of Fire Safety Certificate in r/o **New Kalindi Public School located at J-36, Saurabh Vihar, Badarpur, New Delhi-44.**

Sir,

With reference to your letter no. NKPS/04/22-23 dated 23.04.2022 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 02.05.2022 in the presence of Ms. Manisha (Owner's daughter) and it was observed that the school is running at ground + 02 upper floors of the building which is comprised of ground + 03 upper floors. During the inspection following shortcomings were observed:-

1. School is not accessible to fire engine as approach road width is less than 6.0 meters.
2. Fire extinguishers found removed.
3. First aid hose reels found non function.
4. Fire pump found non functional.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(Sunil Chawdhary)

Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.

e/c 8/6
10/5/22