

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/School/2022/SZ/ 252  
To

Dated: 26/05/2022

The Principal,  
SDMC Nigam Pratibha Kanya School,  
Rajokari, New Delhi 110038.

**Sub:** Regarding issuance of Fire Safety Certificate (FSC) in r/o SDMC Nigam Pratibha Kanya School, Rajokari, New Delhi 110038.

Sir,

This has reference with Gmail of dated 07/04/2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 20/05/2022 and observed that the shortcoming intimated vide letter of even no. 3557 dated 14/06/2019 has not been complied yet. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



(SUNIL CHAWDHARY)  
DY. CHIEF FIRE OFFICER (SZ)

Copy to

1. The Director of Education, SDMC, Civic Centre, Minto road, New Delhi 110002.

d/13

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No. F.6/DFS/MS/School/2019/SZ/ 3557

Dated: 14/05/19

To

The Principal,  
SDMC Nigam Prathibha Kanya School,  
Rajokri, New Delhi-110038.

Sub.:- Reg. Renewal of FSC.


Sir,

This is in reference with your letter No. Nil dated 18/03/2019 received through outdoor diary No. 6288 dated 19/03/2019 on the subject cited above. In this connection, the school premise was re-visited by officer concern of this department on 29/05/2019 in the presence of Mrs. Taravati (Principal) and observed that the department issued FSC vide letter no F.6/DFS/MS/School/SZ/1865 dated 19-10-2015 for ground plus one upper floor. School management constructed new building ground plus two upper floors both blocks are interconnect with each other. To verify the status of fire prevention and fire safety measures already provided therein in your presence. During the inspection, the shortcomings observed are as below: -

1. Fire extinguishers provided is not adequate 8 Nos of fire extinguishers required.
2. First aid hose reel required at each floor.
3. Terrace pump with the capacity of 450 LPM and 40m head required at terrace on auto mode.
4. Overhead tank capacity of 10,000 liter not provided at terrace.
5. Exit sign not provided at each floor.

In view of above shortcomings, renewal of FSC cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department for further consideration in the matter.

Yours faithfully,

  
Atul Garg  
Chief Fire Officer  
Tel.011-23414250

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.