

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/SZ/2022/HTL 20

Dated: 27/05/2022

To

The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi.

Regarding renewal of Fire Safety Certificate in respect of M/s Park Inn by Radisson located at 1 & 2, Ring Road, Lajpat Nagar-IV, New Delhi-24.

Sir,

With reference to online application no. 2022042908849 dated 29.04.2022 on the subject cited above, it is informed that the guest house was inspected by a team of officer concerned from this department on 20.05.2022 in the presence R.K. Mondal (Liasoning Manager) & Mr. Murshid Alim (Sec. Manager) and it was observed that building is comprised of Basement + Ground + Mezzanine + 04 upper floors. During inspection, following shortcomings were observed:-

- 1. Fire check door not provided in basement.
- 2. Ventilation in common area at all floors is not adequate.
- 3. First-aid-hose reels found non functional.
- 4. Internal hydrant systems not provided at ground floor.
- 5. MOEFA found non functional.
- 6. Automatic sprinkler systems found non functional.
- 7. Terrace fire pump found not in auto mode.
- 8. Overhead tank having capacity 7,000 liters is provided against the requirements of 25,000 liters.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Copy to:-.

The Licensee,

M/s Park Inn by Radisson located at 1 & 2, Ring Road, Lajpat Nagar-IV, New Delhi-24.