

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

F.6/DFS/MS/GH/2022/SZ/ 426

Dated: 31./.05.../2022

The Joint Commissioner of Police, 1st Floor, P.S Defence Colony New Delhi 110049.

Regarding issuance of NOC in r/o M/s Mayur Restaurant and Lodging located at A-68, Chittranjan Park, New Delhi 110019

Sir.

This is in reference with MHA Portal ID 2021082819398 dated 16/11/2021 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 18.05.2022 in the presence of Mr. Vikash of the Guest House. During the inspection, it was observed that the Guest House is running Ground + Three Upper Floors. The shortcomings observed are as below:

- 1. There is one staircase having width of 1.0 mtr. The minimum widths of two staircases are required 1.50 mtr each as per UBBL-2016.
- 2. Fire check doors not provided in the building as per clause 7.31 of UBBL 2016.
- 3. Smoke management system not provided as per clause 7.31 of UBBL 2016.
- 4. First Aid Hose Reel provided but not in working.
- 5. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
- 6. The MOEFA system is not provided.
- 7. Terrace level Fire Pump not on auto mode.
- 8. Overhead tank capacity 2000 ltrs provided against the required capacity of 20,000 ltrs.
- The Exit Signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

DELHI FIRĚ SERVICE

Copy to:-

1. M/s Mayur Restaurant and Lodging located at A-68, Chittranjan Park, New Delhi 110019