

C58

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS : DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2022/ 432

Dated: 02/06/2022

To

The Joint Commissioner of Police (Licensing),
1st Floor, Police Station Defence Colony,
New Delhi.

Sub: Regarding renewal of Fire Safety Certificate in respect of **M/s Shezan Place** situated at **1331, Chitli Qabar Chowk, Jama Masjid, Delhi.**

Sir,

With reference to online application I.D. no. 2022040405437 dated 04.04.2022 on the subject cited above, it is informed that the guest house was inspected by Assistant Divisional Officer (SPM) from this department on 19.05.2022 in the presence Mr. Faizal Zamal (Owner's Son). During inspection, following shortcomings were observed:

1. CO detectors not provided as required in gazette notification dated 27.05.2019.
2. First Aid Hose reel found non functional.
3. Occupancy at fourth floor is not allowed as per gazette notification dated 27.05.2019.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

The applicant is requested to rectify the shortcomings at the earliest for further action.

Yours faithfully,


31/5/22

(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Tel: 011-23412025

Copy to:-

The Licensee, M/s Shezan Place at 1331, Chitli Qabar Chowk, Jama Masjid, Delhi.

o/c
31/5