

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No. F.6/DFS/MS/ Restt WZ/2022/ 419

Dated: - 14/06/2022

To,

Sh. Sumit Kumar, Licensing,  
Connaught Plaza Restaurants Pvt. Ltd.,  
McDonald Restaurant, M2K Multiplex,  
Pitampura, New Delhi.

Sub:- Regarding extension of time for rectification of deficiencies in McDonald Restaurant located at M2K Multiplex, Pitampura, New Delhi.

Sir,

This has reference to your e-mail received vide id sumit.kumar@del.in.mcd.com dated 03.06.2022, on the subject cited above. In this connection, it is to inform you that the aforesaid eating house has been inspected on 27.05.2022 by the officer concerned of this department and shortcomings were issued vide letter No. DFS/DO(West)/2022/Directions/137 dated 27.05.2022 with the directions to comply the shortcomings up to 03.06.2022. The restaurant was again re-inspected by the officer concerned of this department but no progress was observed. An e-mail was received to this department for grant of 15-20 days to comply the shortcomings.

Now this department has considered your request & advice to comply the shortcomings up to 23.06.2022 (20 days) and till such time, running of restaurant is at your risk & responsibility.

Yours faithfully,

(Atul Garg)  
Director

Delhi Fire Service

Copy to:-

1. The DHO, North DMC, Keshav puram Zone, New Delhi.

9c

458

**FORM 'P': FORM OF NOTICE**  
[See section 34 (1)/43(2) of the Act]  
[See sub-rule (6) of rule 41]

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE,**  
**NEW DELHI-1100 01**

No. DFS/DO(West)/2022/Directions/137

Dated: 27/05/2022

NOTICE FOR CARRYING OUT THE DIRECTIONS OF THE NOMINATED AUTHORITY

I M.K. Chattopadhyay, DO (West), the Nominated Authority/Director appointed under the Act, on the basis of inspection conducted by me on 27-05-2022, do hereby call upon you to undertake the following Fire Prevention and Fire Safety measures in building/premises- McDonalds Family Restaurant, M2K Multiplex, Pitampura, New Delhi- 110034.

1. Alternate exit door in ground & 1<sup>st</sup> floor found closed.
2. Basement floor is also using as McDonald's store. It should be segregated with fire check door.
3. Access to the alternate staircase found closed.

Above action should be completed latest by 03.06.2022.

  
27/5/2022  
(M.K. Chattopadhyay)  
Nominated Authority  
Delhi Fire Service

To

1. The Occupier/Owner, M/s. McDonald's Family Restaurant, M2K Multiplex, Pitampura, New Delhi.
2. The Dy. Health Officer, North DMC, Kesav Puram Zone, New Delhi