



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/WZ/2022/ 1571

Dated: - 29/06/2022

To,

The Authorized Signatory,  
Kabeer Textiles Pvt. Ltd.,  
Plot no. D-1, Udyog Nagar,  
Rohtak Road, Delhi-110041.

**Subject: Regarding renewal of Fire Safety Certificate in r/o M/s. Kabeer Textiles Pvt. Ltd. Located at Plot no. D-1, Udyog Nagar, Rohtak road, Delhi-110041.**

Sir,

This has reference to your letter no. nil dated 19.05.2022 on the subject cited above. In this connection, it is to inform you that the above said building has been inspected by the officer concerned of this department from fire safety point of view on 13.06.2022 in the presence of Sh. Mahesh Chand Gupta (Owner) to check the shortcomings issued by this department vide letter no. F6/DFS/MS/2019/WZ/5101 dated 22.08.2019.

During the course of inspection it has been observed that the Management has rectified some of the shortcomings the status is under:-


S. no.	Shortcomings	Status
1.	Hose Reel Hose provided but found nonfunctional	Rectified
2.	Automatic Sprinkler System in basement but found nonfunctional	Rectified
3.	Fire Pump of 1800 LPM capacity provided but found nonfunctional	Rectified

In addition of the above, following shortcomings were also observed:-

1. Port Cabin structure at terrace shall be removed.
2. Fire check door found removed at basement floor.
3. Overhead water storage tank is 10,000 ltrs capacity against required 20,000 ltrs.
4. Exit signages are provided but not adequate.

In view of the above shortcomings, renewal of FSC is not considered & rejected. You are requested to submit point wise compliance & till such time occupancy of the building/premises in absence of requisite fire safety arrangements at your own risk and responsibility.

Yours faithfully,

  
(Dharampal Bhardwaj)  
Dy. Chief Fire Officer  
(West Zone)