## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

Dated 27/06/2022

To

The Dy. Health Officer, SDMC Public Health Officer. South Zone, Najafgarh Zone, Najafgarh, Delhi-110043

NO. F-6/DFS/MS/EH/2022/429

Sub: - Regarding issuance of fire safety certificate in r/o M/s Tata Starbucks Pvt Ltd (A Unit of Starbucks Coffee A Tata Alliance) located at Shop No 17, Ground Floor, Woldmark-1, Assest Area No 8, Hospitality District, IGI Airport Delhi 110037

Sir.

This has reference to your MHA Portal ID No. 2022020901877 dated 09/02/2022 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 10.06.2022 in the presence of Mr. Rajeev Kumar (Shift Manager) to verify the fire safety measures installed in the building and observed that restaurant running at ground floor only. During inspection, following points were observed:

1. There are two exits having width of 1.50 m & 1.0 m against the required width of 1.50 mtr each respectively.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

DELHI FIRE SERVICE

Copy to:-

The Joint Commissioner of Police, Lic/Branch, 1st Floor, P S Defence Colony, New Delhi -110049. For taking necessary action on the matter.