GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/DFS/MS/SZ/2021/ 2545

Dated: 03/12021

To,

Ms. Sonalika Jiwani

Dy. Commissioner (HQ-IV)

5. Sham North Mars. Dallai

5, Sham Nath Marg, Delhi

Subject: Annual/ Bi- Annual Joint Inspection of PVR Cinema Located at Pacific mall, Dwarka Sec -21, New Delhi.

Madam/Sir,

This has reference to the letter no. PS/DC (HQ-IV/2021/43 dated 21/10/2021 on the subject mention above. In this connection the joint inspection of above cinema was carried out by the team of officers concerned of this department on 09/11/2021 along with representatives of DDMA, electrical dept. and other agencies etc. The following shortcomings are observed.

- 1. Smoke management system found not functional in auto mode. It must be functional in auto mode.
- 2. Smoke discharging ducts are found open in stairs.
- 3. Lift lobby & FCD found removed at service lift.
- 4. Flashers are found not provided.

The Cinema Management is requested to comply the shortcomings under intimation with this department for further consideration in the matter.

Yours faithfully

Director

Delhi Fire Service

Copy to: -

1. Sh. Pankaj Roy Gupta SDM, Old Delhi road, Kapas hera, New Delhi 120037.

2. The Manager, PVR Cinema, Pacific mall, Dwarka Sec – 21, New Delhi.