

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

E-34

No.F6/DFS/MS/NDZ/2022/ 558

Dated:-11/07/2022

To

The Manager  
M/S Hariday Palace, Guest House,  
3649, Gali Ram Nath Patwa,  
Dariba Pan, Pahar Ganj,  
New Delhi.

Sub: Regarding issuance of FSC in r/o M /S Hariday Palace, Guest House, located at, 3649, Gali Ram Nath Patwa, Dariba Pan, Pahar Ganj, New Delhi.


Sir,

This has reference to online ID No. 2022052811526 dated 28.05.2022, on the subject cited above. In this connection, it is to inform you that the site was inspected by the officers concerned of this department on 30/06/2022 in the presence of **Sh. Anand** and following shortcomings were observed:-

1. Smoke management is not provided as per gazette notification dated 27.05.2019.
2. CO detectors are not provided as per gazette notification dated 27.05.2019.
3. Hose reel found non functional.
4. Pump not in auto mode start provision.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings for further consideration in the matter.

Yours faithfully

  
(S.K. Dua)  
Dy. Chief Fire Officer  
Delhi Fire Service

Copy to :-

1. The Addl. Commissioner of Police (Lic.), Licensing Unit, Defense Colony Police Station, New Delhi