



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/NDZ/2022/ 484

Dated:-2.7../2022

To

The Manager, M /S Sandoz Restaurant Pvt Ltd, P- 23/90 Ground floor Rai building, Connaught Place, New Delhi,

Sub: Regarding issuance of FSC in r/o M/S Sandoz Restaurant Pvt Ltd, at located at P- 23/90 Ground floor, Corner Shop, Rai building, Connaught Place, New Delhi, ID NO. 2022062013225 dated 21.06.22.

Sir,

This has reference to online ID No. 2022062013225 dated 21.06.22 on the subject cited above. In this connection it is to inform you that the site was inspected by the officers concerned of this department on 13/07/2022 in the presence of Manager and following shortcomings were observed:-

- 1. 02 exits of 1.0 meter width are provided against the requirements of 2 exit of 1.5 meter each.
- 2. 01 Staircases of 1.0-meter width is provided against the requirements of 2 staircase of 1.5 meter each.
- 3. First aid hose reel and hydrant systems are not provided.
- 4. MOEFA is not provided.
- 5. Terrace pump of 450 LPM is not provided.
- 6. Overhead fire water tank of 20,000 liter capacity is not provided.
- 7. The complete set of building plan of the restaurant having all details such as area, location of staircase, exit, etc with duly signed by architect is not uploaded.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings at the earliest for further consideration in the matter.

Yours faithfully

DIRECTOR Delhi Fire Service

## Copy to:-

- 1. The Addl. Commissioner of Police (Lic.), Licensing Unit, Defense Colony Police Station, New Delhi.
- 2. DHO, NDMC, Palika Kendra, New Delhi.