## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

F6/DFS/MS/2022/ 1978

Dated:-03.18/2022

To,

Sh. Vivek Shukla, The World Trade Tower, Barakhamba Lane, Connaught Place, New Delhi.

Sub:- Regarding renewal of FSC in r/o World Trade Tower, Barakhamba Lane, Connaught Place, New Delhi.

Sir,

This has reference to your mail id no.<hnegi@thelalit.com>dated 05/07/2022 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 15/07/2022 in the presence of Sh. M.S. Bhandari (Estate Manager) and Mr. H.S. Negi and the following shortcomings were observed:-

- 1. Approach to the building for fire vehicle is obstructed by tree branches required to be pruning.
- 2. Detectors to be provided in left out area.
- 3. MOEFA to be provided in left out area
- 4. PA system found not clearly audible.
- 5. Smoke management system in basement found non functional.
- 6. Fire pumps not in auto start provision.
- 7. Exit signages found inadequate.

Therefore, you are requested to rectify the above shortcomings at the earliest under intimation to this department. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statuary/licensing authority may take suitable action as deemed fit.

You DIRECTOR Delhi Fire Service

Copy to:-

- 1. The Chief Architect, NDMC, Palika Kendra, New Delhi.
- 2. Sh. H.S Negi, Liasion Officer, Bharat Hotel Limited, Barakhamba Avenue, Connaught Place, New Delhi.