



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/School/2022/559

Dated: 12/09/2022

To

The Principal,
The Baptist Convent Sr. Sec. School,
CGHS Complex, I.P. Extn. Patparganj, Delhi-92.

Sub: Regarding Renewal of FSC in r/o The Baptist Convent Sr. Sec. School, CGHS Complex, I.P. Extn. Patparganj, Delhi-92.

Sir,

This has reference to your letter no. BCS/FIR/DFS/2022 dated 04/08/2022 on the subject cited above. In this regard, it is to inform you that the premises was re-inspected by the officer concerned of this department on 06/09/2022 in the presence of Mrs. Alka (Care-taker) and Mr. Mohit Sharma (PTI) and no progress was seen on the observations communicated by this department vide letter no. F6/DFS/MS/School//2019/NDZ/4816 dated 09/08/2019 (photo copy enclosed).

Hence, the Fire Safety Certificate cannot be considered at this stage. The occupancy of the building/ premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner /occupier. Statutory authority may taken action as deemed fit at their end please.

Yours faithfully

Encl:- as above.

(S.K. Dua)

Dy. Chief Fire Officer Delhi Fire Service

Mw

8h/

Copy to:-

The Director (Education), Govt. of NCT, Old Sectt. Delhi - 54. GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. 12/18/ m.s/schal/2019/48/6 Dated: 09/08/19

To,

The Principal,
The Baptist Convent School, C.G.H.S.
Complex, I.P. Exten., Patpargang, Delhi-92.

**Sub:** - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o The Baptist Convent School, C.G.H.S.Complex, I.P. Exten., Patpargang, Delhi-92.

Madam.

This is in reference to your letter no. BCS/DFS/2019 Dated- 16/05/19 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above-mentioned school from fire safety point of view in presence of Mrs. Mahima (Principal). The school building is comprised of ground plus four upper floors. During the course of inspection, the following points / shortcomings were noticed: -

- 1. First Aid Hose reels provided but not functional in each floor...
- 2. Down-comer system provided but not functional.
- 3. Fire pump having 450 LPM provided but not functional.
- 4. Overhead water tank \$25,000 ltrs.capacity not provided.
- 5. The porta cabin constructed on the terrace floor should be removed. In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours

Chief Fire Officer

Ofclo

Copy to:-

 The Joint Director Education(Land & Estate), Directorate of Education, Lucknow Road Delhi-54.