

C-225

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2022/ 51
To,

Dated: 14/8/22

Sh. D. R. Garg,
Maharaja Agrasen Technical Education Society,
PSP Area, Plot no 1, Sec-22, Rohini,
Delhi- 110085.

Sub: Issue of FSC in r/o Block 7 & 8, Maharaja Agrasen Technical Education Society, PSP 1, Sec-22, Rohini, Delhi-110085.

Sir,

This is in reference to your letter No. MATES/DFS/2022/1676 dated 13.04.2022 received through outdoor diary no. 470 dated 18.04.2022 on the subject cited above. The premise was inspected by the concern nominated authority of this department on **02.06.2022**, in presence of **Sh. Arun Rai (Civil Engineer)** to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for renewal of FSC is rejected under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. 6m road all around the building of high rise block found reduced on two sides.
2. Electrical shafts found not sealed throughout from basement to top floor.
3. Fire check doors found removed.
4. Lift lobby and its pressurization found removed in class building.
5. Terrace pump is not working and auto start found remove.
6. FCD in not provided in electrical shaft.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under:
http://www.delhi.gov.in/wps/wcm/connect/doiit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doiit_fire/FIRE/Home/Forms

Yours faithfully


(Atul Garg)

DIRECTOR

Ph; 011-23414000

